Task Control Summary – Oldbury Energy to Waste					
Version: 1	Date:				
on of Lighting Busbar	·				
S	Date:				
	Date:				
i		Version: 1 Date: ion of Lighting Busbar Date:			

The following health, safety and environmental controls must be followed at all times during these works:

- Ensure that all correct means of working at height is used
- Check for sharp edges and the correct protective gloves must be worn
- Ensure work area is clear of rubbish
- Check that the emergency route is clear and accessible
- Make sure all areas are cleaned and waste removed before leaving
- Ensure adequate lighting, if not use separate task lighting Wear Emcor standard PPE plus glasses and gloves

This task control summary must not be more than 1 page be briefed to all those working on this package of works by the supervisor nominated at the top of this form, who is also responsible for day to day compliance with its contents, and with all relevant HSE Controls identified in the Project Plan. It can contain instructions, photographs, sketches or anything needed to communicate the safe system of work for this task

Briefing Record			
Number:	Version:	Date	:
Name	<u>'</u>	Signature	