Task Control Summary – Oldbury Energy to Waste							
Number: 002		Version: 1		Date:			
Scope of works	Installation	of Conduits & Baske	et				
Name of Supervisor	lan Moss		Dat	te:			
Reviewed by (VINCI Manager)	K Bird		Dat	te:			

The following health, safety and environmental controls must be followed at all times during these works:

- Ensure that all correct means of working at height is used
- Check for sharp edges and the correct protective gloves must be worn
- Ensure work area is clear of rubbish
- Check that the emergency route is clear and accessible
- Ensure adequate number of operatives are used for manual handling
- Ensure conduit vise is on level ground
- Appropriate PPE must be worn when using a chop saw
- Only competent personal must change chop saw blade
- Firefighting equipment must be near cutting area and a hot works permit issued
- Be aware of other contractors when moving lengths of conduit & basket around
- Make sure all areas are cleaned and waste removed before leaving
- Ensure adequate lighting, if not use separate task lighting
- Wear Emcor standard PPE plus glasses and gloves

This task control summary **must not be more than 1 page** be briefed to all those working on this package of works by the supervisor nominated at the top of this form, who is also responsible for day

Briefing Record					
Number:	Version:	Date	:		
Name	<u>'</u>	Signature			