

Signed:

Print Name:

Kevin Flint

## EMCOR, EMR BUILDING, OLDBURY

## HEALTH AND SAFETY RISK ASSESSMENT RECORD – NUMBER RA002

Site/Premis Work Activ	Site/Premises: EMR . Area/Section: EMR Building Work Activity: Installation of Lighting Busbar											
		ii oi Lighting bus	CLASSIFICATION ✓Yes		✓ No							
PERSONS AFFECTED			✓Yes ✓ N	0	Experienced		V 1 CS	V NO				
Other Worke	Employees Other Workers			√ ·		Inexperienced		<b>✓</b>				
Public	13			· ·	/	Disabled			<b>√</b>			
Comments: ONLY TRAINED OPERATIVES TO USE EQUIPMENT												
HAZARD T		01210111,20	I O COLLQUII	✓Yes ✓ N	0			√Yes	√ No			
Physical Inju				<b>✓</b>		Biological (e.g. Micro Organism)			<b>✓</b>			
	d (e.g. Harmful Sı	ubstance)				Natural (e.g. Weather)			✓			
Comments: CORRECT PROCEDURES TO BE USED												
IDENTIFIED HAZARDS – tick as appropriate												
Contact with	tact with: a) Moving Machinery Parts ✓		✓	Fire Weather		Weather						
	b) Movir	ng Materials	✓	Explosion			Temperature		✓			
	c) Movin	ng Vehicles	✓	Burns		Manual Handling thts ✓ Lone Working			✓			
	d) Fixed	Machinery		Falls from Hei	ights							
Electrical:	a) Shock	·		Pressurised Sy			Hand Tools		✓			
	b) Burns			Vibration			Confined Spaces					
	c) Explo	sion		Noise			Restricted Access	/Egress				
Radiation:	a) Ultrav			Harmful Substances Power Tools		C	✓					
	b) Ionisii			Vermin			Sharp Objects		<b>✓</b>			
	c) Lasers	-		Particles		<b>✓</b>	Posture		<b>✓</b>			
Comments:	0) = 32 51 5			]		<u> </u>						
	d x Severity =	Risk Score. S	Score assumi	ng standard	con	trol measu	res overleaf are	implem	ented = 2			
	NT RISK IDENT							-				
		tut's and abrasions	ID CHID ANGE	ON C	1.0	135			1 1			
	STATUTORY	PROVISIONS (AD	ND GUIDANCE	(Note: Standa	rd Co	ntrol Measur	es must also be revie	wed and n	<u>iade site</u>			
specific)	07/ PPF Regs 1	002 PHWFR 1	008 Managemen	t of Health & Sa	fety V	Work Reas 100	9, C.O.S.H.H. 2002 D	langerous (	Substances			
		egs 2002, Construct			iiciy v	voik Regs 177	), C.O.B.H.H. 2002 B	angerous	Substances			
and Empressi	• ramospiiores re	.go <b>2</b> 00 <b>2</b> , constr <b>uc</b>	ion 2 toign mana	5000000								
	IRED FOR TASI	K (tick/complete as	appropriate – F	Refer to Contro	l Mea		ge making specific)					
Hard Hat		<b>✓</b>	Ear Protection			Welding Helmet						
Safety Footwear		<b>✓</b>		Goggles		Respirator (enter typ		)				
High Vis Vest		<b>√</b>	Overalls	, 1			Gloves (3)		✓			
Gas Welding			Safety Spec				Other (specify type)					
Circle Resid	ual Risk Score af	ter implementatio	n of your additio									
		a		Risk Score =		Acceptable – unlikely to cause first aid case injury, risk			ıry, risk to			
	Likelihood Severity of Injury			LOW			or environmental dan		• •			
of	LOW 1	MED 2	IIICII 2				nlikely to cause lost tir					
Harm	LOW 1	MED 2	HIGH 3	LOW			or environmental dan	nage. Wor	k to be			
	Possible first	Possible <3 day	Possible >3	Risk Score =			competent person. se serious injury, risk	to boolth r	ronarty or			
	aid case	lost time injury,	day serious	LOW			damage. Control meas					
	injury,	minor	injury, major	LOW			nt must be in place.	suics and v	VIIII			
	environmental	environmental	environmental		11	ictiod stateme	in must be in place.					
	damage	damage	damage									
Unlikely 1	1	2	3	Risk Score =	4 P	ossible risk of	lost time injury, mino	r injury to	health,			
				MEDIUM			damage. Supervision,					
					W	vritten method	statement must be in j	olace.				
Possible 2 2		4	6	Risk Score =	6 L	Unacceptable – revisit work procedures to reduce t		ce this risk				
				HIGH		o a score of for	ır or below					
Likely 3		9	Risk Score =		Unacceptable – refer the operation to the Manager							
				HIGH		responsible. The work must not proceed as propo		oosed, an				
					a	Iternative meth	nod must be developed	l				

Position in Company: Operations Director

Date: 14-03-13

Date of Review: 07-03-13

AGILE BUILING SERVICES LIMITED – PROJECT SPECIFIC RISK ASSESSMENTS



## EMCOR, EMR BUILDING, OLDBURY

No p	AILS OF CONTROL MEASURES bersons are to work on installing conduits and trays unless they have indeed a Tool Box talk detailing the Risks associated with this operation	Is this control measure in place	Additional action required
1.	Check for sharp edges, wear protective gloves to protect hands and give a better grip.	√	
2.	Ensure that the correct means of working at height is used. Use podiums or scaffold towers when possible.	<b>√</b>	
3.	Do not use stepladders as a working platform at any stage.	<b>√</b>	
4.	Ensure that suitable hand protection is provided to protect operatives from sharp cut ends.	<b>√</b>	
5.	Use 110v or battery powered chop saw or equal to cut containment trays and all threaded supporting rods.	<b>✓</b>	
6.	Use eye protection	<b>√</b>	
7.	Manage vibration and noise by intermittent use only.	<b>√</b>	
8.	First Aid cover is available at all times.	<b>√</b>	
9.	Ensure work area is clear of rubbish, other contractors etc.	<b>√</b>	
10.	Check that the emergency route is clear and easily accessible to operatives carrying out task.	<b>√</b>	
11.	Full supervision to be given whilst work is in progress.	✓	



## EMCOR, EMR BUILDING, OLDBURY

Name:	Signature:	Date: