

1 shape
CAD file (STL facets)

2 layer
slice of thickness Δz

3 path
contour + layer hatching



4 voxel
spot × track × Δz

The part is no longer stored in a mould but in a file: shape, then layers, then paths, then voxels.