

1 heat the slab
(steel ≈ 1200 °C)



2 roll passes: thickness down,
length up, volume kept



3 coil the strip
(sheet 1–20 mm, foil < 0.2 mm)