
filament
drive gears
hot end, 200–400 °C
x, y
roads cool and weld to the layer below