casting



geometry stored in
the mould

forging



geometry stored in
the dies

machining



geometry stored in
the tool path

additive



geometry stored in
the layer file