
1 soft steel part
2 austenitise ≈ 850 °C
3 quench in water:
martensite, hard, brittle
4 temper 200–600 °C:
hard and tough