

1 heat the slab
(steel ≈ 1200 °C)

2 roll passes: thickness down,
length up, volume kept

3 coil the strip
(sheet 1–20 mm, foil < 0.2 mm)