	Casting	**Forging**	**Milling**	**Additive**
	primary shaping, from liquid	*forming, cohesion kept*	*separating, cohesion reduced*	*primary shaping, layer by layer*
				
geometry stored in	**the mould and pattern**	**the dies**	**the tool path (CNC program)**	**the layer path (sliced CAD file)**
tooling	patterns, moulds: medium to high	hardened dies: high	fixtures and tools: low	none specific to the part
material used per part	part + gates, risers; recycled	part + flash; near net shape	stock $\gg$ part: up to 10–20$\times$ in aerospace	part + supports; powder largely reused
economic batch	tens to millions	thousands and more	one to thousands	one to hundreds