
heat-affected zone
1 two plates, a V groove
2 arc melts wire and edges
3 weld bead, one part