

1 soft steel part

2 austenitise ≈ 850 °C

3 quench in water:
martensite, hard, brittle

4 temper 200–600 °C:
hard and tough