
piston or screw
paste: ceramic slurry, clay, mortar
beads set by drying or hydration
each bead must carry the next layer