
CONVENTIONAL

Pressing and sintering


compact the powder in a die, then bond it in a furnace



ADDITIVE

Laser powder bed fusion

a laser melts each powder layer where the part is



DIN 8580 primary shaping 1.4 · from the granular or powder state