

13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address - See Remit to Information)

www.seabird.com

+1-425-643-9866

Service Request 1005522738

 Date
 04-APR-2025

 Sales Order
 321319312

CUSTOMER INFORMATION

SERVICE REPORT

Name: NOAA - LA JOLLA LABORATORY

Account: 40280288 ANTHONY COSSIO

ANTHONY.COSSIO@NOAA.GOV

858-546-5609

Bill To Address

NOAA - LA JOLLA LABORATORY 8901 LA JOLLA SHORES DRIVE SOUTHWEST FISHERIES SCIENCE CENTER LA JOLLA,CA,92037,US PO Number:

Phone

EA-133M-15-CQ-0039/1305M325F0054

Ship To Address

NOAA - LA JOLLA LABORATORY 8901 LA JOLLA SHORES DRIVE SOUTHWEST FISHERIES SCIENCE CENTER LA JOLLA,CA,92037,US

PRODUCT INFORMATION

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16245

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3 INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	1
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED.	

Un	bil	led	Ite	ms



SERVICE REPORT

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date Sales Order

Phone

04-APR-2025 321319312

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

Phone

Service Request

Sales Order

Date

1005522738

04-APR-2025

321319312

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1755

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date **Sales Order**

Phone

04-APR-2025

321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16567

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request Date Sales Order

04-APR-2025 321319312

Phone

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16564

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

 Date
 04-APR-2025

 Sales Order
 321319312

Phone

Service Request

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1889

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND	1
	ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date **Sales Order**

Phone

04-APR-2025 321319312

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16247

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

321319312

Date 04-APR-2025 **Sales Order**

Phone

Service Request

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1788

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

321319312

Date 04-APR-2025 **Sales Order**

Phone

Service Request

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16239

Special Notes Problems Found:

The conductivity was found to have excessive drift.

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration. Replaced the conductivity cell.

Replaced the O-rings.

Performed a hydrostatic pressure test. Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
801854	SBE37 V2.5 CONDUCTIVITY CELL ASSEMBLY	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date Sales Order

Phone

04-APR-2025 321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-21145

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

 Date
 04-APR-2025

 Sales Order
 321319312

Phone

Service Request

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-2318

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date Sales Order

Phone

04-APR-2025

321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-21148

Special Notes

Problems Found:

The conductivity was found to have excessive drift.

The motherboard has failed.

SBE 63-2330 has failed un-repairable. This sensor will be replaced by s/n 63-4016.

Services Performed:

Perform initial diagnostic evaluation.

Performed pressure calibration.

Performed "POST" cruise calibration.

Replaced the conductivity cell.

Replaced the mother board.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Installed SBE 63, s/n 4016.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item Description	Qty
EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
801542.1.	
COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
REQUIRED.	
	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1. COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3 INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF

Item	Item Description	Qty
41781	SBE37 V4 MOTHERBOARD	1
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
801854	SBE37 V2.5 CONDUCTIVITY CELL ASSEMBLY	1
22096	LITHIUM COIN BATTERY, WITH TABS, BR1632A/HA	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

04-APR-2025 **Sales Order** 321319312

Phone

Service Request

Date

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16306

Special Notes Replaced O-rings.

Performed hydrostatic pressure test.

Services Performed: Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration. Replaced the O-rings. Performed a hydrostatic pressure test. Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	
		1

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

1005522738

Service Request Date Sales Order

Phone

04-APR-2025 321319312

+1-425-643-9866

www.seabird.com

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16242

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

E ANTIFOULANT DEVICE, INCLUDES ONE PN	2
IBRATION FOR SBE37, SB37V2, AND SBE37V3	1
NE MAJOR REPAIR SUCH AS REPLACEMENT OF	
CTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
IPERATURE PRESSURE CHARACTERIZATION IF	
	IBRATION FOR SBE37, SB37V2, AND SBE37V3 NE MAJOR REPAIR SUCH AS REPLACEMENT OF ICTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE IPERATURE PRESSURE CHARACTERIZATION IF

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22096	LITHIUM COIN BATTERY, WITH TABS, BR1632A/HA	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request
Date
Sales Order

Phone

04-APR-2025 321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-21146

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request Date

Phone

04-APR-2025

Sales Order 321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-2320

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request 04-APR-2025

Phone

Date

Sales Order 321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16246

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22096	LITHIUM COIN BATTERY, WITH TABS, BR1632A/HA	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738 04-APR-2025

Service Request Date

Phone

321319312

SERVICE REPORT

Sales Order

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1756

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

04-APR-2025 **Sales Order** 321319312

Phone

Service Request

Date

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16565

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request Date 04-APR-2025 **Sales Order** 321319312

Phone

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1910

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date **Sales Order**

Phone

04-APR-2025

321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16256

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date 04-APR-2025 **Sales Order**

Phone

321319312

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1802

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date Sales Order

Phone

04-APR-2025

321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16238

Special NotesProblems Found:

The conductivity was found to hve excessie drift.

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration. Replaced the conductivity cell.

Replaced the O-rings.

Performed a hydrostatic pressure test. Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3 INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED.	1

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
801854	SBE37 V2.5 CONDUCTIVITY CELL ASSEMBLY	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request

Phone

04-APR-2025

321319312

SERVICE REPORT

Date **Sales Order**

PRODUCT INFORMATION

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16240

Special Notes Problems Found:

The conductity was found to have excessive drift.

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration. Replaced the conductivity cell.

Replaced the O-rings.

Performed a hydrostatic pressure test. Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3 INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED.	1

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
801854	SBE37 V2.5 CONDUCTIVITY CELL ASSEMBLY	1
22096	LITHIUM COIN BATTERY, WITH TABS, BR1632A/HA	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request Date **Sales Order**

Phone

04-APR-2025

321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-16241

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item Description	Qty
EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
801542.1.	
COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
REQUIRED.	
	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1. COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3 INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22096	LITHIUM COIN BATTERY, WITH TABS, BR1632A/HA	1
22096	LITHIUM COIN BATTERY, WITH TABS, BR1632A/HA	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date Sales Order

Phone

04-APR-2025 321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16244

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

Service Request Date Sales Order

Phone

04-APR-2025

321319312

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1754

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request Date Sales Order

Phone

04-APR-2025 321319312

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SMP.36203

Item Description: SBE37SMP-ODO V4, TI, 2000M, MCBH, 5000M ODO

Serial: 37-16243

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
	801542.1.	
SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
	INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
	TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
	SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
	REQUIRED.	

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

www.seabird.com

+1-425-643-9866

1005522738

 Date
 04-APR-2025

 Sales Order
 321319312

Phone

Service Request

SERVICE REPORT

PRODUCT INFORMATION

Item: 63.21

Item Description: SBE63, OPTICAL OXYGEN, MICROCAT, 7000m

Serial: 63-1753

Special Notes

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
SBS-SVC-63	COMPREHENSIVE SERVICE/CALIBRATION OF SBE63, INCLUDING ALL MINOR AND ONE MAJOR REPAIR. INCLUDES STANDARD DISSOLVED OXYGEN CALIBRATION.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

1005522738

Service Request Date Sales Order

Phone

04-APR-2025

321319312

PRODUCT INFORMATION

SERVICE REPORT

Item: 37SMP.36200

Item Description: SBE37SMP, TITANIUM, 2000M, MCBH

Serial: 37-15274

Special Notes

Problems Found:

The conductivity was found to have excessive drift. The temperature was found to have excessive drift.

Services Performed:

Perform initial diagnostic evaluation.

Performed pressure calibration.

Performed "POST" cruise calibration.

Replaced the temperature probe.

Replaced the conductivity cell.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item Description	Qty
EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN	2
801542.1.	
COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3	1
INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF	
TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE	
SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF	
REQUIRED.	
	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1. COMPREHENSIVE SERVICE/CALIBRATION FOR SBE37, SB37V2, AND SBE37V3 INCLDUING ALL MINOR AND ONE MAJOR REPAIR SUCH AS REPLACEMENT OF TEMPERTAURE PROBE, CONDUCTIVITY CELL, OR NON-DIGIQUARTZ PRESSURE SENSOR. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
801854	SBE37 V2.5 CONDUCTIVITY CELL ASSEMBLY	1
801859	SBE37 V3 TEMP PROBE ASSY, FENWAL, 2.265"	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866 www.seabird.com

Service Request 1005522738 04-APR-2025

Sales Order 321319312

Phone

Date

SERVICE REPORT