Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 21148 CALIBRATION DATE: 07-Mar-25 SBE 37 V2 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

a0 = -1.326773e-004 a1 = 3.116828e-004 a2 = -4.730619e-006 a3 = 2.073114e-007

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (counts)	(° C)	(° C)
0.9999	565749.5	0.9999	0.0000
4.4999	484081.1	4.4999	-0.0000
14.9999	309263.6	15.0000	0.0001
18.5000	268027.7	18.4999	-0.0001
24.0000	215335.2	24.0000	0.0000
29.0000	177562.3	29.0000	-0.0000
32.5001	155655.4	32.5001	0.0000

n = Instrument Output (counts)

Temperature ITS-90 (°C) =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

