

Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 21148 CALIBRATION DATE: 17-Mar-25 SBE 37 V2 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

a0 = -1.213367e-004 a1 = 3.088623e-004 a2 = -4.495537e-006 a3 = 2.007480e-007

BATH TEMP (° C)	INSTRUMENT OUTPUT (counts)	INST TEMP (° C)	RESIDUAL (° C)
1.0008	565778.7	1.0008	-0.0000
4.5000	484111.3	4.5000	0.0000
15.0000	309270.3	15.0000	-0.0000
18.5000	268029.8	18.5000	0.0000
24.0000	215334.0	24.0001	0.0001
29.0000	177560.7	28.9999	-0.0001
32.5000	155652.7	32.5001	0.0001

n = Instrument Output (counts)

Temperature ITS-90 (°C) =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

