
ACROBOTIC SevenFortyFun Kit - Parts List

Part	Qty.	Reference	Description
AH.	2	R1, R2	1KΩ 1/4W Resistor
W. C.	2	R3, R8	47KΩ 1/4W Resistor
ALL.	1	R4	5.1KΩ 1/4W Resistor
A. L. L.	1	R5	39KΩ 1/4W Resistor
AL.	1	R6	4.7KΩ 1/4W Resistor
ALL!	1	R7	7.5KΩ 1/4W Resistor
JH.	2	R9, R11	51Ω 1/4W Resistor
ALL.	1	R10	24Ω 1/4W Resistor
330	1	C1	33pF Capacitor (Ceramic)
3904	13	Q1, Q2, Q5, Q6, Q7, Q8, Q9, Q10, Q11, Q12, Q13 Q14, Q16	NPN Transistor (BJT)
3906	7	Q3, Q4, Q15, Q17, Q18 Q19, Q20	PNP Transistor (BJT)
	4		3/16" (dia) x 5/8" Stand-Off
	4		4-40 x 3/16" Machine Screw
	8	-	4-40 x 5/8" Thumb Screw
	2	J1, J9	0.1" Pitch 2x4 Male Shrouded Header
**	1	J9	0.1" Pitch, 1x20-Pin Male Header
	1	-	IDC 2x4 6" Ribbon Cable







For instructions, firmware, files please visit: http://github.com/acrobotic/OA_SevenFortyFun