
(a) Isolated steps
300
200
100
0
Time to 50% [ms]
Measured (down)
Measured (up)
Model O
10
20
40
80
Step size [kPa]
(b) Sustained sine, 40 kPa
Amplitude ratio
1.0
0.5
0.0
Measured
Model O
O + threshold
2
4
6
Frequency [Hz]