


| FILLING POINT | BAY1-PL.5 | BAY1-PL.6 | BAY2-PL.3 | BAY2-BS.4 | BAY3-PTDX.2 | BAY3-PL8 | BAY4-BS.7 | BAY4-BS.11 | BAY5-PL.10 | BAY5-PX.13 | BAY6-PL.16 | BAY7-BS.12 | BAY7-BS.15 | BAY8-PXT.14 |
|---------------|-----------|-----------|-----------|-----------|-------------|----------|-----------|------------|------------|------------|------------|------------|------------|-------------|
| TOTAL | 0 | 0 | 0 | 35 | 2 | 27 | 30 | 12 | 26 | 42 | 25 | 0 | 36 | 3 |



SUMMARY REALISASI PER-PRODUK

 BIOSOLAR
 : 1073KL

 PERTALITE
 : 1058KL

 PERTAMAX
 : 267KL

 PERTAMAX TURBO
 : 18KL

 PERTAMINA DEX
 : 16KL

 DEXLITE
 : 57KL

 TOTAL PENYALURAN
 : 2489KL



BAY1-PL.5

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|----|---------------|-------|--------------|--------|---------------|-------------------|------|
| | | | | | | | |
| | | | TOTAL | 0 | | | |



BAY1-PL.6

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|----|---------------|-------|--------------|--------|---------------|-------------------|------|
| | | | | | | | |
| | | | TOTAL | 0 | | | |



BAY2-PL.3

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|----|---------------|-------|--------------|--------|---------------|-------------------|------|
| | | | | | | | |
| | | | TOTAL | 0 | | | |



BAY2-BS.4

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---------------------------|-----------|--------------|--------|---------------|---------------------|------|
| 1 8122843718, 8122843717 | B9273SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 01:20:55 | |
| 2 8122838519 | BA8097VAU | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 06:18:07 | |
| 3 8122763381, 8122763381 | BH8437YV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 06:39:56 | |
| 4 8122838518 | BH8932HV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 06:24:38 | |
| 5 8122828479 | BH8773XU | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 06:43:18 | |
| 6 8122904596 | BH8635MV | BIOSOLAR B40 | 10000 | BAY2-BS.4 | 2025-05-06 07:43:49 | |
| 7 8122904603, 8122904603 | BH8438HV | BIOSOLAR B40 | 10000 | BAY2-BS.4 | 2025-05-06 08:33:14 | |
| 8 8122903835 | BH8459YW | BIOSOLAR B40 | 5000 | BAY2-BS.4 | 2025-05-06 07:48:38 | |
| 9 8122408928, 8122408929 | BH8434HV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 08:01:58 | |
| 10 8122408932 | BH8314MV | BIOSOLAR B40 | 10000 | BAY2-BS.4 | 2025-05-06 08:35:40 | |
| 12 8122845843 | BH8548YX | BIOSOLAR B35 | 8000 | BAY2-BS.4 | 2025-05-06 10:18:20 | |
| 11 8122408925 | BH8050HV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 09:25:36 | |
| 12 8122903853 | В9894РҮК | BIOSOLAR B40 | 5000 | BAY2-BS.4 | 2025-05-06 09:12:57 | |
| 13 8122847586, 8122847585 | B9221SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 08:42:11 | |
| 14 8122906788 | BH8255MV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 08:48:41 | |
| 15 8122847564, 8122732247 | B9745SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 09:12:01 | |
| 16 8122893559 | B9731SFV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 10:07:29 | |
| 17 8122919139 | BH8876MW | BIOSOLAR B40 | 5000 | BAY2-BS.4 | 2025-05-06 10:51:46 | |
| 18 8122886242, 8122886242 | BH8890MW | BIOSOLAR B40 | 10000 | BAY2-BS.4 | 2025-05-06 10:56:14 | |
| 19 8122886243, 8122886243 | BH8077NV | BIOSOLAR B40 | 10000 | BAY2-BS.4 | 2025-05-06 10:57:03 | |
| 20 8122896701 | B9221SFV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 11:17:25 | |
| 21 8122725999 | B9154SFV | BIOSOLAR B40 | 5000 | BAY2-BS.4 | 2025-05-06 11:25:46 | |
| 22 8122916239 | BH8256MV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 12:22:34 | |
| 23 8122850095 | B9367TFV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 12:27:15 | |
| 24 8122927814, 8122927814 | BH8616MZ | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 12:41:53 | |
| 25 8122808761 | B9486SFV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 14:49:37 | |
| 26 8122872665, 8122872666 | B9787SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 15:53:22 | |
| 27 8122843724, 8122878192 | B9745SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 16:35:41 | |
| 28 8122893560 | B9284SFV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 18:32:23 | |
| 29 8122898776, 8122898777 | B9731SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 20:49:58 | |
| 30 8122850099 | BA8096VAU | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 21:42:34 | |
| 31 8122822668, 8122844728 | B9787SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 22:00:54 | |
| 32 8122850053, 8122850052 | BA9036VU | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 22:02:20 | |
| 33 8122832614, 8122832615 | B9766SFV | BIOSOLAR B40 | 16000 | BAY2-BS.4 | 2025-05-06 22:31:40 | |
| 34 8122893548 | BH8770YX | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 22:40:48 | |
| 35 8122872658 | B9314SFV | BIOSOLAR B40 | 8000 | BAY2-BS.4 | 2025-05-06 23:14:32 | |
| | | TOTAL | 382000 | | | |



BAY3-PTDX.2

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|-----|---------------|----------|----------------------|--------|---------------|---------------------|------|
| 1 8 | 3122905510 | B9171SFV | PERTAMINA DEX 50 PPM | 8000 | BAY3-PTDX.2 | 2025-05-06 14:26:00 | |
| 2 8 | 3122868136 | BH8546YX | PERTAMINA DEX 50 PPM | 8000 | BAY3-PTDX.2 | 2025-05-06 16:48:18 | |
| | | | TOTAL | 16000 | | | |



BAY3-PL.8

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---------------------------|-----------|--------------|--------|---------------|---------------------|------|
| 1 8122791822 | B9673SFV | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 02:20:24 | |
| 2 8122838517 | BA8097VAU | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 06:18:07 | |
| 3 8122841598, 8122841597 | BH8323NV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 06:35:17 | |
| 4 8122898789, 8122898790 | B9035SFW | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 07:34:14 | |
| 5 8122898766 | BH8546YX | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 07:59:31 | |
| 6 8122852785 | B9653SFV | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 08:36:56 | |
| 7 8122886261 | B9820SFU | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 08:51:13 | |
| 8 8122902201, 8122902200 | B9643SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 09:24:53 | |
| 9 8122905509 | B9284SFV | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 09:27:49 | |
| 10 8122896702 | B9221SFV | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 11:17:25 | |
| 11 8122902210, 8122902211 | B9731SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 13:53:53 | |
| 12 8122883236, 8122883235 | B9742SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 15:07:49 | |
| 13 8122890323, 8122890322 | B9273SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 15:29:43 | |
| 14 8122844719, 8122844720 | B9338SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 16:00:20 | |
| 15 8122905507, 8122905508 | B9345TFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 18:23:03 | |
| 16 8122893557 | B9284SFV | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 18:32:23 | |
| 17 8122848872, 8122775698 | B9327TFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 19:09:32 | |
| 18 8122893570, 8122893569 | B9369TFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 19:19:38 | |
| 19 8122890348, 8122890349 | B9171SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 19:46:59 | |
| 20 8122883230, 8122883231 | B9035SFW | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 20:09:14 | |
| 21 8122850045, 8122898773 | BH8040YY | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 21:11:23 | |
| 22 8122908413, 8122908412 | B9477SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 21:17:34 | |
| 23 8122865904, 8122865905 | B9730SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 21:25:36 | |
| 24 8122890314, 8122890313 | B9811SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 21:59:50 | |
| 25 8122893577 | B9273SFV | PERTALITE | 8000 | BAY3-PL.8 | 2025-05-06 22:54:53 | |
| 26 8122903833, 8122865889 | B9445SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 23:06:03 | |
| 27 8122908357, 8122908356 | B9774SFV | PERTALITE | 16000 | BAY3-PL.8 | 2025-05-06 23:12:13 | |
| | | TOTAL | 360000 | | | |



BAY4-BS.7

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|-------------------------------|----------|--------------|--------|---------------|---------------------|------|
| 1 8122849589 -DX | B9049SFW | BIOSOLAR B35 | 8000 | BAY4-BS.7 | 2025-05-06 01:47:39 | |
| 2 8122763380, 8122763380 | BH8319YY | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 06:25:38 | |
| 3 8122871277 | BH8796GU | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 06:52:04 | |
| 4 8122903838 | BH8457YW | BIOSOLAR B40 | 5000 | BAY4-BS.7 | 2025-05-06 07:49:35 | |
| 5 8122898767 | BH8546YX | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 07:59:31 | |
| 6 8122443859 | BH8450XU | BIOSOLAR B40 | 10000 | BAY4-BS.7 | 2025-05-06 08:34:35 | |
| 7 8122408930 | BH8048HV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 08:33:50 | |
| 8 8122849368 | B9653SFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 08:36:56 | |
| 9 8122902209 | B9787SFU | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 09:07:55 | |
| 10 8122893572, 8122893571 | B9035SFW | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 09:39:46 | |
| 11 8122778444 -DX, | BH8548YX | BIOSOLAR B35 | 8000 | BAY4-BS.7 | 2025-05-06 10:18:20 | |
| 12 8122850054 -DX | B9016SFW | BIOSOLAR B35 | 4000 | BAY4-BS.7 | 2025-05-06 10:58:20 | |
| 13 8122878199, 8122878198 | B9224SFV | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 13:02:45 | |
| 14 8122886231, 8122886230 | B9035SFW | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 13:57:21 | |
| 15 8122858986, 8122858985 | B9812SFV | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 14:27:56 | |
| 16 8122821847, 8122883218 | B9787SFU | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 15:02:22 | |
| 17 8122791393 | B9331TFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 15:22:45 | |
| 18 8122898793 -DX | B9957SFV | BIOSOLAR B35 | 8000 | BAY4-BS.7 | 2025-05-06 15:42:48 | |
| 19 8122902203 -DX | B9221SFV | BIOSOLAR B35 | 5000 | BAY4-BS.7 | 2025-05-06 15:45:53 | |
| 20 8122822664 | B9675SFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 15:57:33 | |
| 21 8122883188 -DX | BH8546YX | BIOSOLAR B35 | 8000 | BAY4-BS.7 | 2025-05-06 16:48:18 | |
| 22 8122890345, 8122890346 | B9811SFV | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 17:40:16 | |
| 23 8122898761 | B9314SFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 19:51:06 | |
| 24 8122902208 | B9808SFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 18:41:48 | |
| 25 8122765997 | B9324SFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 19:03:10 | |
| 26 8122872667, 8122872668 | B9336SFV | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 21:10:44 | |
| 27 8122823326 -DX, 8122823329 | B9957SFV | BIOSOLAR B35 | 16000 | BAY4-BS.7 | 2025-05-06 21:22:40 | |
| 28 8122791472 | B9369TFV | BIOSOLAR B40 | 8000 | BAY4-BS.7 | 2025-05-06 22:28:07 | |
| 29 8122903858 -DX, 8122903843 | B9483SFV | BIOSOLAR B35 | 16000 | BAY4-BS.7 | 2025-05-06 22:30:37 | |
| 30 8122792324, 8122792325 | B9284SFV | BIOSOLAR B40 | 16000 | BAY4-BS.7 | 2025-05-06 22:42:31 | |
| | | TOTAL | 320000 | | | |



BAY4-PL.11

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---------------------------|----------|--------------|--------|---------------|---------------------|------|
| 1 8122898785, 8122898784 | B9171SFV | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 09:57:21 | |
| 2 8122890340, 8122890341 | B9838SFV | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 10:33:58 | |
| 3 8122883180, 8122883179 | B9742SFV | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 11:59:06 | |
| 4 8122657110 | B9331TFV | PERTALITE | 8000 | BAY4-PL.11 | 2025-05-06 15:22:45 | |
| 5 8122896694 | B9957SFV | PERTALITE | 8000 | BAY4-PL.11 | 2025-05-06 15:42:48 | |
| 6 8122842248 | B9675SFV | PERTALITE | 8000 | BAY4-PL.11 | 2025-05-06 15:57:33 | |
| 7 8122893587, 8122893588 | BH8548YX | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 19:49:09 | |
| 8 8122790173, 8122790172 | BH8545YX | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 20:01:49 | |
| 9 8122899775, 8122899776 | BH8546YX | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 20:24:51 | |
| 10 8122858427, 8122858428 | BH8066UV | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 22:13:54 | |
| 11 8122890344 | B9369TFV | PERTALITE | 8000 | BAY4-PL.11 | 2025-05-06 22:28:07 | |
| 12 8122791846, 8122844716 | B9324SFV | PERTALITE | 16000 | BAY4-PL.11 | 2025-05-06 23:20:34 | |
| | | TOTAL | 160000 | | | |



BAY5-PL.10

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---------------------------|----------|--------------|--------|---------------|---------------------|------|
| 1 8122763266 | B9750SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 06:43:11 | |
| 2 8122870434 | BH8335TU | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 06:54:48 | |
| 3 8122845813 | B9327TFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 07:21:18 | |
| 4 8122424015, 8122424015 | BH8440HV | PERTALITE | 10000 | BAY5-PL.10 | 2025-05-06 08:39:22 | |
| 5 8122680164, 8122680165 | B9649SFV | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 09:41:12 | |
| 6 8122797864 | B9271SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 10:31:37 | |
| 7 8122850086 | B9016SFW | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 10:58:20 | |
| 8 8122890326 | B9719SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 11:43:52 | |
| 9 8122886256 | B9284SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 13:17:40 | |
| 10 8122858983, 8122858984 | B9649SFV | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 13:54:49 | |
| 11 8122808767 | B9486SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 14:49:37 | |
| 12 8122870559, 8122870560 | B9284SFV | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 15:32:40 | |
| 13 8122778440 | B9336SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 15:54:24 | |
| 14 8122872669 | B9347TFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 15:59:41 | |
| 15 8122896705 | B9271SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 16:33:20 | |
| 16 8122893575, 8122893576 | B9784SFU | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 16:57:20 | |
| 17 8122903866 | B9168SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 17:16:44 | |
| 18 8122902197, 8122902198 | B9742SFV | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 18:41:09 | |
| 19 8122898765 | BH8770YX | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 19:08:57 | |
| 20 8122893550 | B9325TFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 19:16:58 | |
| 21 8122829947 | B9224SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 21:16:23 | |
| 22 8122790171 | B9373TFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 21:19:30 | |
| 23 8122903842, 8122903841 | B9812SFV | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 22:10:12 | |
| 24 8122829984, 8122829985 | B9808SFV | PERTALITE | 16000 | BAY5-PL.10 | 2025-05-06 22:20:01 | |
| 25 8122890312 | BH8770YX | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 22:40:48 | |
| 26 8122890335 | B9201SFV | PERTALITE | 8000 | BAY5-PL.10 | 2025-05-06 22:54:04 | |
| | | TOTAL | 266000 | | | |



BAY5-PX.13

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---|----------|---------------|--------|---------------|---------------------|------|
| 1 8122841040 | B9498SFV | PERTAMAX,BULK | 3000 | BAY5-PX.13 | 2025-05-06 01:21:40 | |
| 2 8122847589 | B9498SFV | PERTAMAX,BULK | 2000 | BAY5-PX.13 | 2025-05-06 01:21:57 | |
| 3 8122849590 | B9049SFW | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 01:47:39 | |
| 4 8122850046 | B9750SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 06:43:11 | |
| 5 8122851471 | BH8726MV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 07:16:26 | |
| 6 8122845814 | B9327TFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 07:21:18 | |
| 7 8122769543 | B9455SFV | PERTAMAX,BULK | 3000 | BAY5-PX.13 | 2025-05-06 09:06:19 | |
| 8 8122890351 | B9455SFV | PERTAMAX,BULK | 1000 | BAY5-PX.13 | 2025-05-06 09:06:36 | |
| 9 8122883192 | B9787SFU | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 09:07:55 | |
| 10 8122890311, 8122898772 | B9414SFV | PERTAMAX,BULK | 3000 | BAY5-PX.13 | 2025-05-06 09:55:15 | |
| 11 8122890315 | B9414SFV | PERTAMAX,BULK | 2000 | BAY5-PX.13 | 2025-05-06 09:55:40 | |
| 12 8122865898 | B9271SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 10:31:37 | |
| 13 8122890329 | B9719SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 11:43:52 | |
| 14 8122850222 | B9367TFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 12:27:15 | |
| 15 8122838287 | B9182TFV | PERTAMAX,BULK | 2000 | BAY5-PX.13 | 2025-05-06 13:00:55 | |
| 16 8122902195 | B9182TFV | PERTAMAX,BULK | 3000 | BAY5-PX.13 | 2025-05-06 13:01:05 | |
| 17 8122886257 | B9284SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 13:17:40 | |
| 18 8122905504 | B9171SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 14:26:00 | |
| 19 8122815703 | B9347TFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 15:59:41 | |
| 20 8122896707 | B9271SFV | PERTAMAX,BULK | 5000 | BAY5-PX.13 | 2025-05-06 16:33:20 | |
| 21 8122903825, 8122903826 | B9774SFV | PERTAMAX,BULK | 16000 | BAY5-PX.13 | 2025-05-06 16:44:50 | |
| 22 8122903867 | B9168SFV | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 17:16:44 | |
| 23 8122893547, 8122947190, 8122876223 | B9507SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 17:56:13 | |
| 24 8122883212, 8122883211, 8122883225, 81228832 | B9418SFV | PERTAMAX,BULK | 4000 | BAY5-PX.13 | 2025-05-06 18:16:43 | |
| 25 8122898771 | B9677SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 18:16:10 | |
| 26 8122785321 | B9673SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 18:33:38 | |
| 27 8122902212 | B9808SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 18:41:48 | |
| 28 8122870563 | B9324SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 19:03:10 | |
| 29 8122898768 | BH8770YX | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 19:08:57 | |
| 30 8122893549 | B9325TFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 19:16:58 | |
| 31 8122898763, 8122792331, 8122872654 | B9542SFV | PERTAMAX,BULK | 7000 | BAY5-PX.13 | 2025-05-06 19:54:09 | |
| 32 8122921134, 8122817620, 8122916311 | B9387SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 21:11:50 | |
| 33 8122843719 | B9224SFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 21:16:23 | |
| 34 8122790165 | B9373TFV | PERTAMAX,BULK | 8000 | BAY5-PX.13 | 2025-05-06 21:19:30 | |
| 35 8122896693, 8122896709, 8122896698 | B9157SFV | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 21:39:41 | |
| 36 8122951790 | B9182TFV | PERTAMAX,BULK | 1000 | BAY5-PX.13 | 2025-05-06 22:45:37 | |
| 37 8122865896 | B9182TFV | PERTAMAX,BULK | 3000 | BAY5-PX.13 | 2025-05-06 22:49:05 | |
| 38 8122951789, 8122766018 | B9503SFV | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 22:49:20 | |
| 39 8122883229 | B9820SFU | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 22:49:20 | |
| 40 8122890347 | B9201SFV | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 22:54:04 | |
| 41 8122903818, 8122876233, 8122951802 | B9455SFV | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 23:32:35 | |
| 42 8122951459, 8122951460, 8122951801 | B9414SFV | PERTAMAX,BULK | | BAY5-PX.13 | 2025-05-06 23:32:58 | |
| | ' | TOTAL | 267000 | | | |



BAY6-PL.9

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|----|---------------|-------|--------------|--------|---------------|-------------------|------|
| | | | | | | | |
| | | | TOTAL | 0 | | | |



BAY6-PL.16

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---------------------------|-----------|--------------|--------|---------------|---------------------|------|
| 1 8122835517 | BH8140MV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 06:39:17 | |
| 2 8122870437 | BH8336TU | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 06:48:51 | |
| 3 8122902184, 8122902183 | B9171SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 07:45:02 | |
| 4 8122408911 | BH8428HV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 08:38:23 | |
| 5 8122890320 | B9224SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 09:26:59 | |
| 6 8122893558 | B9731SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 10:07:29 | |
| 7 8122791845 | B9338SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 10:11:43 | |
| 8 8122878202, 8122878203 | B9766SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 15:40:39 | |
| 9 8122902190, 8122902191 | B9731SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 16:18:38 | |
| 10 8122898791 | B9325TFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 16:50:49 | |
| 11 8122890319, 8122890318 | B9171SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 17:06:55 | |
| 12 8122778441 | B9371TFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 17:18:20 | |
| 13 8122883191 | B9820SFU | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 17:40:57 | |
| 14 8122898770 | B9677SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 18:16:10 | |
| 15 8122828502 | B9673SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 18:33:38 | |
| 16 8122883215, 8122883216 | B9483SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 19:18:44 | |
| 17 8122797863 | BH8544YX | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 19:53:45 | |
| 18 8122898762 | B9314SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 19:51:06 | |
| 19 8122878202, 8122878203 | B9271SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 20:17:55 | |
| 20 8122823323, 8122823322 | B9329TFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 20:36:11 | |
| 21 8122876176, 8122876174 | B9587SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 21:18:25 | |
| 22 8122903821 | BA8096VAU | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 21:42:34 | |
| 23 8122841596, 8122886263 | B9719SFV | PERTALITE | 16000 | BAY6-PL.16 | 2025-05-06 22:05:42 | |
| 24 8122847566 | B9371TFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 22:25:14 | |
| 25 8122872655 | B9314SFV | PERTALITE | 8000 | BAY6-PL.16 | 2025-05-06 23:14:32 | |
| | | TOTAL | 272000 | | | |



BAY7-BS.12

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|----|---------------|-------|--------------|--------|---------------|-------------------|------|
| | | | | | | | |
| | | | TOTAL | 0 | | | |
| | | | TOTAL | Ĭ | | | |



BAY7-BS.15

| No Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|---------------------------|-----------|--------------|--------|---------------|---------------------|------|
| 1 8122826370 | B9673SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 02:20:24 | |
| 2 8122871777, 8122871778 | BH8134OU | BIOSOLAR B40 | 20000 | BAY7-BS.15 | 2025-05-06 06:14:49 | |
| 3 8122763382, 8122763382 | BH8438YV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 06:24:55 | |
| 4 8122768377 | BH8636MV | BIOSOLAR B40 | 10000 | BAY7-BS.15 | 2025-05-06 07:45:54 | |
| 5 8122865894 | B9634PYQ | BIOSOLAR B40 | 5000 | BAY7-BS.15 | 2025-05-06 07:55:51 | |
| 6 8122408926, 8122408927 | BH8013HW | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 08:03:37 | |
| 7 8122408924 | BH8047HV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 08:37:28 | |
| 8 8122408933, 8122408933 | BH8436HV | BIOSOLAR B40 | 10000 | BAY7-BS.15 | 2025-05-06 09:16:53 | |
| 9 8122443860 | BH8934HV | BIOSOLAR B40 | 10000 | BAY7-BS.15 | 2025-05-06 08:38:51 | |
| 10 8122843721, 8122843722 | B9336SFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 08:40:41 | |
| 11 8122906789 | BH8256MV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 08:47:05 | |
| 12 8122804866, 8122898769 | B9034SFW | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 08:54:05 | |
| 13 8122847568 | B9224SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 09:26:59 | |
| 14 8122905506 | B9284SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 09:27:49 | |
| 15 8122844713 | B9338SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 10:11:43 | |
| 16 8122758878, 8122758873 | B9325TFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 10:48:16 | |
| 17 8122903863, 8122903862 | BH8546YX | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 10:50:21 | |
| 18 8122924176 | BH8458YW | BIOSOLAR B40 | 5000 | BAY7-BS.15 | 2025-05-06 11:06:52 | |
| 19 8122847591, 8122893574 | B9273SFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 11:42:08 | |
| 20 8122916238 | BH8255MV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 12:22:04 | |
| 21 8122905505 | B9820SFU | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 12:33:22 | |
| 22 8122886259, 8122890337 | B9490SFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 12:44:27 | |
| 23 8122828453, 8122847579 | B9477SFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 13:03:25 | |
| 24 8122902199 | B9221SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 15:45:53 | |
| 25 8122778452 | B9336SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 15:54:24 | |
| 26 8122883193, 8122883194 | B9035SFW | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 17:10:29 | |
| 27 8122778453 | B9371TFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 17:18:20 | |
| 28 8122680045, 8122797881 | B9201SFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 19:01:36 | |
| 29 8122797811 | BH8544YX | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 19:53:45 | |
| 30 8122815014, 8122864069 | B9331TFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 20:51:47 | |
| 31 8122826368, 8122865901 | B9345TFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 21:27:43 | |
| 32 8122808763, 8122876182 | BA8099VAU | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 21:54:42 | |
| 33 8122826373, 8122826372 | B9677SFV | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 22:03:58 | |
| 34 8122828475 | B9371TFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 22:25:14 | |
| 35 8122794256 | B9273SFV | BIOSOLAR B40 | 8000 | BAY7-BS.15 | 2025-05-06 22:54:53 | |
| 36 8122800352, 8122896706 | B9035SFW | BIOSOLAR B40 | 16000 | BAY7-BS.15 | 2025-05-06 23:36:00 | |
| | | TOTAL | 428000 | | | |



BAY8-PXT.14

| No | Loading Order | Truck | Product Name | Preset | Filling Point | Gate In Timestamp | Note |
|----|---------------|----------|----------------------|--------|---------------|---------------------|------|
| 1 | 8122902182 | B9820SFU | PERTAMAX TURBO, BULK | 5000 | BAY8-PXT.14 | 2025-05-06 10:52:44 | |
| 2 | 8122898786 | B9820SFU | PERTAMAX TURBO, BULK | 5000 | BAY8-PXT.14 | 2025-05-06 15:35:25 | |
| 3 | 8122898792 | B9325TFV | PERTAMAX TURBO, BULK | 8000 | BAY8-PXT.14 | 2025-05-06 16:50:49 | |
| | TOTAL | | | | | | |