



## Darh Generic Requirements Table

BMW AUTOSAR Core 4 Rel. 3 and adaptive BMW AUTOSAR Core Rel. 1 Project

**BMW AG** Author 2017-12-14

Release Date 5.1.0 Version

Release Status

+49 89 382 - 32233 (classic) / +49 89 382 - 22522 (adaptive) Hotline

bac@bmw.de (classic) / abac@bmw.de (adaptive) Contact

> https://asc.bmw.com/jira/browse/BSUP (extern) https://asc.bmwgroup.net/jira/browse/BSUP (intern)

### **Revision History**

Version	Date	Changed by	Description
5.1.0	2017-12-14	JC-42	Version Update
5.0.1	2017-10-12	JC-42	Version Update
5.0.0	2017-06-29	JC-42	Initial version for SP2021

Company Bayerische Motoren Werke Aktiengesellschaft

Postal address BMW AG 80788 München

Office address Forschungs- und Innovationszentrum Hufelandstr. 1

80937 München Telephone Switchboard +49 89 382-0

Internet www.bmwgroup.com





## **Table of Contents**

•	Related documentation	lion	3
_			_

2 Requirements Table 4

### BMW GROUP



#### 1 Related documentation

#### References

[1] LH Diagnosemaster Systembeschreibung SAP: 10000504-000-13





# 2 Requirements Table

The Requirements are taken from [1].

Requirement	Description	Satisfied by
[DMA_PA_4773]	No description	
[DMA_PA_5841]	No description	
[DMA_PA_8584]	No description	
[DMA_PA_9157]	No description	