



Darh Classic Requirements Table

Project BMW AUTOSAR 4 Core Rel. 3

Author BMW AG

Release Date 2017-12-14

Version **5.1.0**

Status Release

Hotline +49 89 382 - 32233

contact bac@bmw.de

https://asc.bmw.com/jira/browse/BSUP (extern) https://asc.bmwgroup.net/jira/browse/BSUP (intern)

Revision History

Version	Date	Changed by	Description
5.1.0	2017-12-14	JC-42	Version Update
5.0.2	2017-11-09	JC-42	Version Update
5.0.1	2017-10-12	JC-42	Version Update
5.0.0	2017-06-29	JC-42	Initial version for SP2021

Company Bayerische Motoren Werke Aktiengesellschaft

Postal address BMW AG 80788 München

Office address Forschungs- und Innovationszentrum (FIZ) Hufelandstr. 1

80937 München **Telephone** Switchboard +49 89 382-0

Internet

Internet www.bmwgroup.com





Table of Contents

1	Related documentation	3
_	De surinamento Table	

2 Requirements Table 4

BMW GROUP



1 Related documentation

References

[1] LH Diagnosemaster Systembeschreibung SAP: 10000504-000-13

BMW GROUP



2 Requirements Table

The Requirements are taken from [1].

Requirement	Description	Satisfied by
[DMA_PA_8248]	No description	
[DMA_PA_8417]	No description	
[DMA_PA_5762]	No description	
[DMA_PA_8415]	No description	
[DMA_PA_9154]	No description	