



# SysTime Classic Requirements Table

BMW AUTOSAR 4 Core Rel. 3 Project

**BMW AG** Author

2017-12-14 Release Date

> 5.0.3 Version

Release Status

+49 89 382 - 32233

bac@bmw.de Contact

> https://asc.bmw.com/jira/browse/BSUP (extern) https://asc.bmwgroup.net/jira/browse/BSUP (intern)

## **Revision History**

Version	Date	Changed by	Description
5.0.3	2017-12-14	JC-42	Version Update
5.0.2	2017-10-12	JC-42	Version Update
5.0.1	2017-08-10	JC-42	BAC-6200: Add integration requirements.
5.0.0	2017-06-29	JC-42	Initial version for SP2021.

Company Bayerische Motoren Werke Aktiengesellschaft

Postal address BMW AG 80788 München

Office address Forschungs- und

Innovationszentrum (FIZ) Hufelandstr. 1 80937 München

Telephone Switchboard +49 89 382-0

Internet

www.bmwgroup.com





### **Table of Contents**

1	Related documentation	3
2	Requirements Table	4

## BMW GROUP



#### 1 Related documentation

#### References

[1] LH Diagnosemaster Systembeschreibung SAP: 10000504-000-13

[2] Diagnose - Systembeschreibung SAP: 10000784-000-12

BMW GROUP



# 2 Requirements Table

The Requirements are taken from [1] and [2].

Requirement	Description	Satisfied by
[DK_T3_1374]	No description	[IM_SysTimeClassic_0006]
		[IM_SysTimeClassic_0007]
[DK_T3_452]	No description	[IM_SysTimeClassic_0006]
[DK_T3_453]	No description	[IM_SysTimeClassic_0006]
[DMA_PA_8300]	No description	[IM_SysTimeClassic_0004]
		[IM_SysTimeClassic_0005]
[DMA_PA_8471]	No description	[IM_SysTimeClassic_0001]
[DMA_PA_8550]	No description	[IM_SysTimeClassic_0003]
[DMA_PA_8551]	No description	[IM_SysTimeClassic_0003]
[DMA_PA_8552]	No description	[IM_SysTimeClassic_0002]
		[IM_SysTimeClassic_0003]