



SysTime Generic Requirements Table

Project BMW AUTOSAR Core 4 Rel. 3 and adaptive BMW AUTOSAR Core Rel. 1

Author BMW AG

Release Date 2017-12-14

Version **5.0.3**

Status Release

Hotline +49 89 382 - 32233 (classic) / +49 89 382 - 22522 (adaptive)

Contact bac@bmw.de (classic) / abac@bmw.de (adaptive)

https://asc.bmw.com/jira/browse/BSUP (extern) https://asc.bmwgroup.net/jira/browse/BSUP (intern)

Revision History

Version	Date	Changed by	Description
5.0.3	2017-12-14	JC-42	Version Update
5.0.2	2017-10-12	JC-42	Version Update
5.0.1	2017-08-10	JC-42	BAC-6200: Add integration requirements.
5.0.0	2017-06-29	JC-42	Initial version for SP2021.

Company Bayerische Motoren Werke Aktiengesellschaft

Postal address BMW AG 80788 München Office address

Forschungs- und Innovationszentrum (FIZ) Hufelandstr. 1 80937 München

Telephone Switchboard +49 89 382-0

Internet www.bmwgroup.com







Table of Contents

1	Related documentation	3
2	Requirements Table	4

BMW GROUP



1 Related documentation

References

[1] LH Diagnosemaster Systembeschreibung SAP: 10000504-000-13

[2] Diagnose - Systembeschreibung SAP: 10000784-000-12

BMW GROUP



2 Requirements Table

The Requirements are taken from [1] and [2].

Requirement	Description	Satisfied by
[DK_T3_452]	No description	
[DK_T3_453]	No description	
[DMA_PA_8451]	No description	
[DMA_PA_8460]	No description	
[DMA_PA_8471]	No description	
[DMA_PA_8550]	No description	
[DMA_PA_8551]	No description	
[DMA_PA_8552]	No description	
[DMA_PA_8471]	No description	[IM_SysTime_0002]
[DMA_PA_9033]	No description	[IM_SysTime_0001]