

## Readme CBD1400351

## Workaround

## **Using MICROSAR Safe Silence Verifier (MSSV)**

For errors in osekasm.h please refer to *MicrosarOs\_Rh850\_SafetyManua*l, chapter 9.1.

There you can find some instructions for apply MSSV.exe on the OS sources.

For errors in Compiler\_Cfg.h please start MSSV.exe with following parameters:

MSSV.exe -i <SourcePath> -i <GenPath> -i <HeaderPath> -D NOASM

Please use MSSV.exe in folder Generators/MSSV and ignore Generators/MSSV\_legacy