
ECE 1188 Lab 6 Report Adam Brower

1.




2.

At router RSSI: -37 5 foot RSSI: -41 10 foot RSSI: -43

The RSSI value decreased the further from the router I got

3.



- 4. MQTT Communication: https://youtube.com/shorts/BoqOnz72ZCU?feature=share
- 5. I will be submitting late for part 5 because of EXPO thank you so much