

Livox Mid-360S Release Notes

Date:	2026.07.15
Livox Mid-360S Firmware:	V35.1.0112 (MD5: 31ac720142fad7d5b58ed6c6fea33f34)

What's New

- Added IMU range configuration options. For related settings, refer to the Livox Wiki communication protocol.
- Fixed some known issues.

Livox Mid-360S Release Notes

Date:	2026.04.15
Livox Mid-360S Firmware:	V35.1.0111 (MD5: 4e1c33d6505f75462cf4949f494875af)

What's New

- Added configuration for motor low-speed mode.
- Added a switch to control point cloud transmission when time synchronization is interrupted.
- Added fault detection and reporting capabilities.