

Commercial Kitchen Solutions Inc

SERVICE REPORT

Work Order: WO-388179 | Date: 05/30/2025

Client Information

Client	Miller and Sons
Address	864 Nancy Landing, New Michael, SC 47665
Phone	(213)224-0547

Equipment Information

Field	Value
Machine Type	Fryers
Model	CrispKing 300
Serial Number	SN13820432

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Amanda Foster
Technician ID	TECH-019
Certification	Factory Certified Specialist
Arrival Time	01:46
Labor Hours	3.88

Technician Signature: _____ **Date:** _____

Commercial Kitchen Solutions Inc | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com