

Restaurant Equipment Services LLC

SERVICE REPORT

Work Order: WO-385963 | Date: 10/23/2025

Client Information

Client	Vega Ltd
Address	05483 Lee Junctions Apt. 630, Port Jessicashire, DE 49239
Phone	514-981-4652

Equipment Information

Field	Value
Machine Type	Fryers
Model	OilGuard Elite
Serial Number	SN62491084

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Carlos Rodriguez
Technician ID	TECH-008
Certification	Master Technician Level 3
Arrival Time	21:06
Labor Hours	2.42

Technician Signature: _____ **Date:** _____

Restaurant Equipment Services LLC | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com