

# Metro Kitchen Equipment Service

## SERVICE REPORT

Work Order: WO-365883 | Date: 04/24/2025

### Client Information

Client	Duran and Sons
Address	33663 Castillo Locks, Wilkinsonport, PR 34819
Phone	(985)731-5376x357

### Equipment Information

Field	Value
Machine Type	Fryers
Model	CrispKing 300
Serial Number	SN90877546

### Service Details

#### Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

#### Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

### Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

## Technician Information

---

<b>Technician Name</b>	Carlos Rodriguez
<b>Technician ID</b>	TECH-008
<b>Certification</b>	Master Technician Level 3
<b>Arrival Time</b>	12:36
<b>Labor Hours</b>	0.58

---

**Technician Signature:** \_\_\_\_\_ **Date:** \_\_\_\_\_

---

*Metro Kitchen Equipment Service | 24/7 Service | (555) 123-4567*

*www.foodservicetech.com | service@foodservicetech.com*