


Object size and overlap: where the measurements accumulate



All PLA objects; identical bins and color limits. Grey = zero exported objects in a measurement bin. Associations may reflect segmentation geometry.