Pump maintenance, section 4: check the seal every 500 hours.
Torque the bolts to 45 Nm (33 ft-lb) in a star pattern.
Café filter – replace at 25 °C; warranty § 3.2 applies.