

LABORATORY EQUIPMENT

Inspection & Testing Equipment Register

53 instruments in service, with calibrated measuring ranges — as of 12 August 2026

NO.	TEST EQUIPMENT	MANUFACTURER	MEASURING RANGE
1	Proces V/mA calibrator, model 715	FLUKE	Input: (0 ÷ 25,000) V; (0 ÷ 24,000) mA Output: (0 ÷ 20,000) V; (0 ÷ 24,000) mA Current loop voltage: 24 VDC
2	Loop Calibrator, model 705	FLUKE	Input: (0 ÷ 28,000) V; 0 ÷ 24,000) mA Output: (0 ÷ 24,000) mA Uloop: 24 VDC
3	Volt/mA Calibrator, model MS 7221	MASTECH	Input: (0 ÷ 10,000) V; (0 ÷ 24,000) mA Output: (0 ÷ 10,000) V; (0 ÷ 24,000) mA Uloop: 24 VDC
4	Calibrator, model 724	FLUKE	Input: (0 ÷ 30,000) V; (0 ÷ 24,000) mA; (0 ÷ 3200,0) Ω Output: (0 ÷ 10,000) V; (0 ÷ 24,000) mA; (15,0 ÷ 3200,0) Ω Inp./Out-Thermo couple: E, J, K, T, R, S, B, L, U, N, mV Inp/Out - RTD: Pt 100, Pt 200, Pt 500, Pt 1000; Ni120 - 672 Uloop: 24 VDC, 22 mA
5	Temperature calibrator KOMPAVI 5	H&B ELIMA	(-100,00 ÷ 100,00) mV; (-25,00 ÷ 25,00) mA Thermo elements: K: (-270 ÷ 1370) °C; T: (-270 ÷ 400) °C J: (-210 ÷ 1200) °C; N: (-270 ÷ 1300) °C R: (-50 ÷ 1770) °C; S: (-50 ÷ 1770) °C
6	Temperature calibrator TC – 650	TEK KNOW	(50 ÷ 650) °C
7	Configurator, HART- USB modem	JSP Industrial Controls	USB 1.1 /140 mA
8	Notebook ASUS 1011CX with HART software	ASUS	—
9	Micromanometer; type: 18A10.100.02	THOMMEN	(0 ÷ 1) bar
10	Manometer	TGL	(0 ÷ 250) kPa [(0 ÷ 2,5) bar]

NO.	TEST EQUIPMENT	MANUFACTURER	MEASURING RANGE
11	Manometer	TGL	(0 ÷ 400) kPa [(0 ÷ 4) bar]
12	Manometer	TGL	(0 ÷ 1) MPa [(0 ÷ 10) bar]
13	Manometer	BORAC	(0 ÷ 16) bar [(0 ÷ 1,6) MPa]
14	Manometer	TGL	(0 ÷ 2,5) MPa [(0 ÷ 25) bar]
15	Manometer	TGL	(0 ÷ 40) kp/cm ² [(0 ÷ 40,8) bar]
16	Manometer	TGL	(0 ÷ 10) MPa [(0 ÷ 100) bar]
17	Manometer	TGL	(0 ÷ 25) MPa [(0 ÷ 250) bar]
18	Manometer	TGL	(0 ÷ 40) MPa [(0 ÷ 400) bar]
19	Manometer	TGL	(0 ÷ 100) MPa [(0 ÷ 1000) bar]
20	Digital Pressure Gauge type CPG1000	WIKA	(0 ÷ 70) bar
21	Digital Pressure Gauge type CPG1000	WIKA	(-1 ÷ 2) bar
22	Pneumatic Calibrator FF 1091 PLUS – LP – 220	TRANSMATION - USA	Input: (-50,00 ÷ 50,00) V; (-50,00 ÷ 50,00) mA Output: (0,00 ÷ 11,00) V; (0,00 ÷ +22,00) mA Uloop: 24 VDC / 20 mA
23	Pressure transducer TN 23344 P-3	TRANSMATION - USA	(0 ÷ 5) psig [(0 ÷ 0,34474) bar]
24	Pressure transducer TN 23344 P-6	TRANSMATION - USA	(0 ÷ 50) psig [(0 ÷ 3,4474) bar]
25	Pressure transducer TN 23344 P-14	TRANSMATION - USA	(0 ÷ 500) psig [(0 ÷ 34,474) bar]
26	Pressure transducer TN 23344 P-20	TRANSMATION - USA	(0 ÷ 5000) psig [(0 ÷ 344,74) bar]
27	Hydraulic test device with weights	A DRUCK - USA	(5 ÷ 700) bars; Medium - oil ST55 $\Delta p = 0,002 \% / ^\circ C$ Calibration gravity: 9,80665 m/s ²
28	Pneumatic test device with weights type: RUD-YPR 9608019, model: T 3400 A/B;	WIKA	(0,2 ÷ 30) bar; [(-0,03 ÷ 1) bar]
29	Calibrator indicator /for pressure/ type: DPI 610 PS	Druck - England	Pressure: (-1 ÷ 20) bar / 20 mA Input: (0 ÷ 50) VDC; (0 ÷ 55) mA Output: 10VDC; (0 ÷ 24) mA
30	Phase tester PeakTech 2530	PeakTech	(40 ÷ 690) V~; (15 ÷ 400) Hz
31	Clamp meter KEW2056R	KYORITSU	(0 ÷ 1000) A~; (0 ÷ 1000) A=

NO.	TEST EQUIPMENT	MANUFACTURER	MEASURING RANGE
32	Clamp MS2125A	Mastech	(0 ÷ 1000) A [~] ; (0 ÷ 1000) A=
33	LV Tester M 5010	BBC - GOERZ METRAWATT	Per manufacturer's technical manual / specification
34	Megaohmmeter MI 2077 TERA OHM 5kV	Metrel	(0,12 MΩ ÷ 5 TΩ); (250 ÷ 5000) V
35	LV tester PROFITEST 2 - M520W	GOSSEN METRAWAT	Per manufacturer's technical manual / specification
36	Earth resistance clamp MS2301	MASTECH	(0,01 ÷ 1200) Ω
37	Wheatstone bridge ML0120	ISKRA	(0,05 Ω ÷ 500 kΩ)
38	Megaohmmeter 7016 IN	SEW	(0,00 MΩ ÷ 30 TΩ); (500 ÷ 15000) V; Step: 500 V
39	Eurotest XE, MI 3102H BT	Metrel	Insulation resistance: (0.00 MΩ ÷ 999 MΩ); Utest: 500/1000 V 0.00 MΩ ÷ 19.99 GΩ; Utest: 2500 V Continuity: (0.00 Ω ÷ 1999 Ω) Earth resistance: (0.00 Ω ÷ 9999 Ω) RCD test: Time, Current Zloop: (0.00 Ω ÷ 9.99 kΩ) Zline: (0.00 Ω ÷ 9.99 kΩ)
40	Microohmmeter RMO200G	IBEKO Power AB	Itest (100 ÷ 200) A: (0 ÷ 9999) μΩ Itest (50 ÷ 100) A: (0,00 ÷ 20,00) mΩ Itest (20 ÷ 50) A: (0,00 ÷ 50,00) mΩ Itest (10 ÷ 20) A: (0,00 ÷ 99,99) mΩ, Itest: 10 A (0,0 ÷ 500,0) mΩ Itest 5 A: (0,0 ÷ 999,9) mΩ
41	Test device for testing protection relays UNITEST 60	UNITEHNA - Odžaci	(0 ÷ 60) A [~] ; (0 ÷ 250) V [~] =; 250 VA
42	Test device for testing protection relays UNITEST 2000	UNITEHNA - Odžaci	(0 ÷ 2000) A [~] , 2000 VA
43	Test device for testing protection relays UNITEST 4000	UNITEHNA - Odžaci	(0 ÷ 4000) A [~] , 6300 VA
44	Test device for testing protection relays UNITEST 30F-3	UNITEHNA - Odžaci	3 x (0 ÷ 30) A [~] ; (3 X 60; 3 X 250) V [~]

NO.	TEST EQUIPMENT	MANUFACTURER	MEASURING RANGE
45	VLF Tester HVA45TD	b2 electronics	Voltage: VLF truesinus: (0 - 32,3) kVrms / (45,0 kVpeak) VLF square voltage: (0,0 ÷ 34,0) kV DC Voltage: ± (0,0 ÷ 34,0) kV; Step: 0.1 kV Frequency: (0,01 ÷ 0,1) Hz; Step: 0,01 Hz Time duration: h:min:sec (00:00:00. ÷ 24:00:00) TanDelta: 0,0001 ÷ 0,99 % Utest: VLF truesinus: 0,01 Hz ÷ 0,1 Hz 0,0 kVpeak ÷ 45,0 kVpeak /(0,0 kVrms ÷ 32,3 kVrms/ Cable sheath test: Test voltage: max. 10 kV Time: 1 min ÷ 15 min Current: 0.1 mA - 5.0 mA Resistance: 0,1 MΩ ÷ 25 TΩ Capacity: 0,0 pF ÷ 10,0 μF
46	AC/DC HV test set	BAUR	(0 ÷ 25) kV=; (0 ÷ 45) kV~; / max. 4,7 μf /
47	Earth clamp tester KEW 4202	Kyoritsu	(0,00 ÷ 1580) Ω; 0,4 mA ÷ 30,0 A)
48	Luxmeter FT3424	Hioki	(0,00 ÷ 1000) lx
49	Eurotest 61557, MI 2086	Metrel	Insulation resistance: (0.000 ÷ 199,9) MΩ; Utest: 250 V (0.000 ÷ 1000) MΩ; Utest: 1000 V (0.000 ÷ 19999) MΩ; Utest: 2500 V Continuity: (0.00 Ω ÷ 1999 Ω) Earth resistance: (0.00 Ω ÷ 9,999 kΩ) RCD test: Time, Current Zloop: (0.00 Ω ÷ 9,99 kΩ) Zline: (0.00 Ω ÷ 9,99 kΩ)
50	CE MultiTester MI 2094	Metrel	HV Test: (0.100 ÷ 5.000) kV; (0.0 ÷ 500.0) mA Continuity ltest 25 A: (0.000 ÷ 9.999) Ω Insulation resistance: (0.000 ÷ 999) MΩ

NO.	TEST EQUIPMENT	MANUFACTURER	MEASURING RANGE
51	Step Contact Voltage Measuring System MI 3295	Metrel	Step voltage/Touch voltage: (0,01 mV ÷ 59.9 V) Current: (0.00 ÷ 99.9) A Earth resistance: (0.001 ÷ 199,9) Ω
52	LCR metar PeakTech 2175	PeakTech	Resistance: (0,000 Ω ÷ 110 MΩ) Capacity: (11 nF ÷ 110 mF) Inductance: (11 mH ÷ 20 H)
53	Thermohygrometer MS 6508	Mastech	Ambient temperature: (-20 ÷ 60) °C Relative Humidity: (0 ÷ 100) %RH Minimum humidity temperature: (-20 ÷ 60) °C Dew point temperature: (-50 ÷ 60) °C

Technical manager of the laboratory

Sretko Marjanović