

## Ummsaid Bakery Dubai Branch

P.O Box No: 353497, DIFC - 2, Dubai - UAE  
Tel: +971 4 3833 303; Email: contact@ummsaid.ae

## Quotation Comission - Fleet Vehicles

Date: 15-03-2023

Sr.No.	Supplier Name	Item Description	UOM	Specification	Quotation reference	Requested Qty.	UOM	Price quoted (AED)	Price Negotiated (AED)	Total purchase. cost(AED)	Remarks
1	Royal smart	Wheel bearing,brakepad,leaf bush	Nos	K-77236	EST1-002469	1	Nos	1,220.00	1,220.00	1,220	Lowest price, Quality, Service
2	Right solution	Wheel bearing,brakepad,leaf bush	Nos	K-77236	EST1-008644	1	Nos	1,947.00	1,947.00	1,947	
3	Accenture	Wheel bearing,brakepad,leaf bush	Nos	K-77236	EST1-034638	1	Nos	1,945.00	1,945.00	1,945	
4											
5											
6											
7											
8											
9											
10											
<b>Total</b>											
<b>Selected Vendor</b>											
Sr.No.	Supplier Name	Item Description	UOM	Specification	Quotation reference	Requested Qty.	UOM	Price quoted (AED)	Price Negotiated (AED)	Total purchase. cost(AED)	Remarks
1	Royal smart	Wheel bearing,brakepad,leaf bush	Nos	K-77236	EST1-002469	1	Nos	1,220.00	1,220.00	1,220	Lowest price, Quality, Service
2											
3											
4											
5											
6											

## Criteria for selection

- ▲ Quality
- ▲ Service
- ▲ Lowest price
- ▲
- ▲

Prepared By (Procurement)

Approved By (Deputy General manager)

Effective Date: 01-FEB-2023

Document No: USB PUR 0003 Version 1

SIGN: *[Signature]*  
P. Alhami Pathoor  
Deputy General Manager




رویل سمارت  
لتصییح المركبات

00049.12n

**ESTIMATE**

---

TRN : 10052822960003

NAME : MR. ISHAM	NO. : EST1-002469				
COMPANY : UMM SAID BAKERY DUBAI BRANCH	DATE : 09/12/2022				
TRN# : 1003871210003	REF. NO. :				
ADDRESS : Building 25 - Plot 363, 29, Dubai Investment Park Second, Dubai	EST. DAYS : 0				
PHONE : +971 4 883 3303	PAYMENT TERMS :				
REGISTRATION : 77236 DXB-K	MAKE & MODEL : TOYOTA HIACE	YEAR : 2017	CHASIS NO. :	K.M / MILES : 0	
SI. No.	Description	Qty	Rate	VAT	Amount
<b>LABOUR CHARGES</b>					
1	FRONT BOTH SIDE WHEEL BEARING CHANGING CHARGE	2	100.00	5.00	210.00
2	FRONT WHEEL BRAKE OVERHAULING REPLACING DAMAGE PARTS	1	80.00	4.00	84.00
3	REAR RH SIDE LEAF BUSH CHANGING	1	50.00	2.50	52.50
<b>SPARE PARTS</b>					
	FRONT BOTH SIDE WHEEL BEARING	2	245.00	12.25	511.50
	FRONT BRAKE PAD SET (KEY VALUE)	1	200.00	10.00	210.00
	LATHE CHARGE:- DISC POLISHING	2	25.00	1.25	52.50
	LATHE CHARGE:- LEAF BUSH AND WHEEL BEARING PRESSING	3	25.00	1.25	78.75
	REAR RH SIDE LEAF BUSH	1	75.00	3.75	78.75
<div style="text-align: right;">    <b>Hazique Mohamed</b>          Asst/ Manager Sales &amp; BD       </div>					
 SIGN: Abraham Aloor DATE: 11/12/2022 APPROVED BY: General Manager					
Sub Total : 1,220.00					
Net Total Excl. VAT (AED) : 0.00					
VAT 5% : 61.00					
Net Total Incl. VAT (AED) : 1,281.00					
AED ONE THOUSAND TWO HUNDRED EIGHTY-ONE ONLY					

This is a Computer generated Estimate and needs no signature.

**TERMS & CONDITIONS:**

1. A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
  2. Delivery subject to availability of Parts.
  3. Part prices are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

Approved by :

FOR ROYAL SMART AUTO REPAIRING

Created by : SARUN

**MOSSMAN 597-564, DIP-2, DUBAI, U.A.E, TEL: +971 4 5915757, P.O BOX: 474387**  
**royalsmartauto@gmail.com, www.royalsmartauto.ae**

RIGHT SOLUTION AUTO REPAIR  
 Dubai Investment Park - 2  
 Tel: 04 2721821, P.O Box: 72818  
 Email: contact@rightsolution.ae  
 www.rightsolution.ae



### REPAIR ESTIMATE

ATTN. :				No. : EST1-008644	
Party Name : UMMSAID BAKERY Dubai				Date : 09/12/2022	
Address : DIP 2, DUBAI, UAE					
Phone : +97148833303					
Fax : +97148878751					
Reg. No.	Vehicle Make & Type	Model	K.M.	Engine No.	Chasis No.
77236 DXB	TOYOTA HIACE	2018	300,000		JTFPX22POJ0081848
Sl. No.	Job Description				Amount
1	FRONT BOTH SIDE WHEEL BEARING REPLACEMENT WITH SPARE PARTS AND LATHE CHARGE				670.00
2	SELECTOR SEAL REPLACEMENT WITH SPARE PARTS (L+P)				120.00
3	RADIATOR TOP HOSE REMOVING AND REFIXING AND HOSE NEW MAKING CHARGE-OUTSIDE WORK				210.00
4	FAN MOTOR ASSEMBLY DENSO O2Nos REPLACEMENT WITH SPARE PARTS				647.62
5	REVERSE SWITCH REPLACEMENT WITH SPARE PARTS (L+P)				60.00
6	REAR RIGHT SIDE SIDE SPRING LEAF BUSH REMOVING AND REPLACEMENT WITH SPARE PARTS AND LATHE CHARGE				240.00
7	NOTE:- BRAKE SHOE NEED TO REPLACE ON NEXT SERVICE (MINOR)				
Less Discount :					
Total Labour Charges					
Total Spare Parts					
Outside Work					
Others					
Gross Amount					1,947.62
VAT Amount (5%)					97.38
Net Amount					2,045.00
Dhs. : TWO THOUSAND FORTY-FIVE AND XX / 100					

Remarks :

User ID : User1  
 This is a Computer generated Estimate and needs no signature.

#### TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
2. Delivery subject to availability of Parts.
3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

This Quotation valid for 15 days only

For RIGHT SOLUTION AUTO REPAIR



Tel.:04 - 8878253  
 Fax:04 - 8878254  
 P.O. Box :77387  
 DIFC Phase 2, Dubai - U.A.E.  
 Email:accenture@eim.ae

### REPAIR ESTIMATE

No. : EST1-034638

TRN: 100331803500003

ATTN. :  
 Party Name : UMMSAID BAKERY DUBAI BRANCH  
 Address :  
 Phone : 048833303  
 Fax :  
 TRN : 100387712100003

Date : 08/12/2022  
 Reg No. : 77236 DXB-K  
 Make : TOYOTA HIACE  
 Model : 2017  
 Engine No. :  
 Chassis No. : JTFPX22P0J0081848  
 Km. : 299,434

Sl. No.	Job Description	Amount
01	CHARGES FOR FRONT FRONT WHEEL BEARING 2 NOS , FRONT BRAKE PAD SET NEW REPLACING [ SPARE PARTS / LATHE CHARGE + LABOUR ]	870.00
02	CHARGES FOR LOWER ARM BALL JOINT 2 NOS [ JAPAN ] , UPPER ARM ASSY 2 NOS [ JAPAN ] NEW REPLACING [ SPARE PARTS + LABOUR ]	925.00
03	CHARGES FOR GEAR BOX REAR OIL SEAL NEW REPLACING [ SPARE PARTS + LABOUR ]	150.00
<i>Remarks :</i>		
Dhs. : TWO THOUSAND FORTY-TWO AND 25 / 100		
		Total Labour Charges
		Total Spare Parts
		Outside Work
		Others 1,945.00
		Total Amount 1,945.00
		Discount
		VAT (5%) 97.25
		Net Amount 2,042.25

User ID : NITHIN

This is a Computer generated Estimate and needs no signature.

For ACCENTURE AUTOMOTIVES GARAGE

#### TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
2. Delivery subject to availability of Parts.
3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

This Quotation valid for 15 days only

**Umm Said Bakery Dubai Branch**

P.O. Box No: 380487, DIFC - Dubai - U.A.E  
Tel: +971 4 8833 303, Email: contact@umssaid.ae

**Quotation Comparison - Fleet Vehicles**

Date: 15-03-2023

S.No.	Supplier Name	Item Description	UoM	Specification	Quotation reference	Requested Qty.	UoM	Price quoted (AED)	Price Negotiated (AED)	Total purchase cost (AED)	Remarks
1	Royal smart	Ac condenser , fan motor	Nos	U-34398	EST1-002296	1	Nos	670.00	647.62	648	Lower price, Quality, Service
2	Right solution	Ac condenser , fan motor	Nos	U-34398	EST1-008657	1	Nos	647.62	647.62	648	
3	Accenture	Ac condenser , fan motor	Nos	U-34398	EST1-034384	1	Nos	830.00	830.00	830	
4											
5											
6											
7											
8											
9											
10											
<b>Total</b>											

**Selected Vendor**

S.No.	Supplier Name	Item Description	UoM	Specification	Quotation reference	Requested Qty.	UoM	Price quoted (AED)	Price Negotiated (AED)	Total purchase cost (AED)	Remarks
1	Royal smart	Ac condenser , fan motor	Nos	U-34398	EST1-002296	1	Nos	670.00	647.62	648	Lower price, Quality, Service
2											
3											
4											
5											
6											
						1					

**Criteria for selection**

- ▲ Quality
- ▲ Service
- ▲ Lowest price
- ▲
- ▲

Prepared By (Procurement)



Effective Date: 01-FEB-2023

Approved By (Deputy General manager)



Approved

Sign

APPROVED

By: [Signature]

DA



رويال سمارت  
لتصليح المركبات

### ESTIMATE

TRN : 10052822960003

00081.12

NAME : MR. ISHAM	NO. : EST1-002296																			
COMPANY : UMM SAID BAKERY DUBAI BRANCH	DATE : 13/12/2022																			
TRN# : 10052822960003	REF. NO. :																			
ADDRESS : Building 25 - Plot 363, 29, Dubai Investment Park Second, Dubai	EST. DAYS : 0																			
PHONE : +971 4 883 3303	PAYMENT TERMS :																			
REGISTRATION : 89171 DXB-V	MAKE & MODEL : TOYOTA HIACE	YEAR : 0	CHASIS NO. :	K.M / MILES : 0																
Sl. No.	Description	Qty	Rate	VAT	Amount															
1	LABOUR CHARGES CONDENSOR FAN MOTOR CHANGING	1	120.00	6.00	126.00															
	SPARE PARTS CONDENSOR FAN MOTOR	2	275.00	13.75	577.50															
																				
<table border="1"> <tr> <td>Remarks : AED SIX HUNDRED EIGHTY ONLY</td> <td>Hazique Mohamed Asst/ Manager Sales &amp; BD</td> <td>Sub Total : 670.00</td> </tr> <tr> <td></td> <td></td> <td>Less Discount : 22.38</td> </tr> <tr> <td></td> <td></td> <td>Net Total Excl. VAT (AED) : 647.62</td> </tr> <tr> <td></td> <td></td> <td>VAT 5% : 32.38</td> </tr> <tr> <td></td> <td></td> <td>Net Total Incl. VAT (AED) : 680.00</td> </tr> </table>						Remarks : AED SIX HUNDRED EIGHTY ONLY	Hazique Mohamed Asst/ Manager Sales & BD	Sub Total : 670.00			Less Discount : 22.38			Net Total Excl. VAT (AED) : 647.62			VAT 5% : 32.38			Net Total Incl. VAT (AED) : 680.00
Remarks : AED SIX HUNDRED EIGHTY ONLY	Hazique Mohamed Asst/ Manager Sales & BD	Sub Total : 670.00																		
		Less Discount : 22.38																		
		Net Total Excl. VAT (AED) : 647.62																		
		VAT 5% : 32.38																		
		Net Total Incl. VAT (AED) : 680.00																		

This is a Computer generated Estimate and needs no signature.

#### TERMS & CONDITIONS:


- A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
- Delivery subject to availability of Parts.
- Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

Approved by :

FOR ROYAL SMART AUTO REPAIRING

Created by : SARUJ

RIGHT SOLUTION AUTO REPAIR  
 Dubai Investment Park - 2  
 Tel: 04 2721821, P.O Box: 72818  
 Email: contact@rightsolution.ae  
 www.rightsolution.ae



**RIGHT  
SOLUTION**

**REPAIR ESTIMATE**

ATTN. :  
 Party Name : UMMSAID BAKERY Dubai  
 Address : DIP 2,DUBAI, UAE  
 Phone : +97148833303  
 Fax : +97148878751

No. : EST1-008657

Date : 12/12/2022

Reg. No.	Vehicle Make & Type	Model	K.M.	Engine No.	Chassis No.
89171 DXB-V	TOYOTA HIACE	0	280,000		JTFPX22P4H0073214

Sl. No.	Job Description	Amount
1	FAN MOTOR DENSO 02Nos REPLACEMENT WITH SPARE PARTS	647.62
	Less Discount :	
	Total Labour Charges	
	Total Spare Parts	
	Outside Work	
	Others	
	Gross Amount	647.62
	VAT Amount (5%)	32.38
	Net Amount	<b>680.00</b>

Dhs. : SIX HUNDRED EIGHTY AND XX / 100

Remarks :

User ID : User1  
 This is a Computer generated Estimate and needs no signature.

**For RIGHT SOLUTION AUTO REPAIR**

**TERMS & CONDITIONS:**

1. A Supplementary Estimate will be submitted, IF any additional damage/Parts required after dismantling.
  2. Delivery subject to availability of Parts.
  3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.
- This Quotation valid for 15 days only



Tel.:04 - 8878253  
Fax:04 - 8878254  
P.O. Box :77387  
DIFC Phase 2, Dubai - U.A.E.  
Email:accenture@eim.ae

### REPAIR ESTIMATE

No. : EST1-034384

TRN: 100331803500003

ATTN. :  
Party Name : UMMSAID BAKERY DUBAI BRANCH  
Address :  
Phone : 048833303  
Fax :  
TRN : 100387712100003

Date : 11/11/2022  
Reg No. : 89171 DXB-V  
Make. : TOYOTA HIACE  
Model : 2017  
Engine No. :  
Chassis No. : JTFPX22P4H0073214  
Km. : 0

Sl. No.	Job Description	Amount
01	LABOUR CHARGES FOR COOLING FAN MOTOR 2 NOS [ DENSO JAPAN ] NEW REPLACING	100.00
02	SPARE PARTS : - COOLING FAN MOTOR 2 NOS [ DENSO JAPAN ], COOLING FAN LEAF 1	730.00
<i>Remarks :</i>		
Dhs. : EIGHT HUNDRED SEVENTY-ONE AND 50 / 100		Total Labour Charges 100.00
		Total Spare Parts
		Outside Work
		Others 730.00
		Total Amount 830.00
		Discount
		VAT (5%) 41.50
		Net Amount 871.50

User ID : RITHIN

This is a Computer generated Estimate and needs no signature.

For ACCENTURE AUTOMOTIVES GARAGE

#### TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
2. Delivery subject to availability of Parts.
3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

This Quotation valid for 15 days only