

# PURCHASE ORDER

Gulf United Real Estate

PO Box: 1444, Al Meena Street

Doha Qatar

Email: Tel:44415000 Fax: 44438137



PURCHASE ORDER DETAILS				TERMS & CONDITIONS				
PO No.	5520100301	PO Date	29/12/2022	Pay Term	100%AGNINV			
PO Amend No.		Amend Date		Currency	QAR			
PO Status	Open	Type	General	Invoice To	Gulf United Real Estate			
Project Code		Offer No		Pay Mode				
Project Name		Pur Group	104-General	Import	NO			

## SUPPLIER DETAILS

Supplier Name	GULF TEAM TRADING AND CONTRACTING			INCO Terms	DAP-Delivered at Place		
Supplier Code	20304481			Mode of Transport			
Contact Person				Partial Shipment	Yes		
Tel No.	55723016			Transshipment			
Fax	44669318			Remarks			
Mobile	44662691						
Email	suhail@gulf-team.com						

## ITEM DETAILS

S.No	PO Line	Item Code and Description	Sh.No	Need Date	UOM	Quantity	Unit Rate	Value
1.1	00010	550002114 - COMPRESSOR REWINDING WORK	0000	10/01/2023	EA	2.00	2,275.00	4,550.00
Gross Price								4,550.00
Grand Total								4,550.00

Amount in Words: Qatari Riyal FOUR THOUSAND FIVE HUNDRED FIFTY and ZERO dirham Only

Delivery Address : Gulf United Real Estate



For Gulf United Real Estate

(Authorized Signatory)

### Document Level Note :

YOUR QUOTATION REFERENCE IS GUC-GTC-25518.02  
BITZER COMPRESSOR REWINDING WORK  
REMOVING OF COMPRESSOR STATOR.  
REMOVING OF ILD COPPER WIRES.  
WINDING, VARNISHING, AND BAKING TILL DESIRED TEMPERATURE OF COPPER  
WINDING.  
REFITTING OF THE STATOR  
9 MONTHS WARRANTY FROM THE OF COMPLETION

GUC COLD STORE  
KINDLY COORDINATE WITH MR. NAVEED 33975704

Created by: Mohamed Sarhan

Approved By:

Khalid Jmaad  
29/12/2022

**Gulf United Real Estate Investments Company**  
**Price comparison for Rewinding Of bitzer compressor GUC cold store.**  
**29-Dec-22**

S.no	ITEM DESCRIPTIONS	GULF TEAM TRADING				ELECTRICAL & REF				GULF LIGHTS			
		UOM	QTY	ORIGINAL PRICE	NEGOTIATED PRICE	ORIGINAL AMOUNT	NEGOTIATED AMOUNT	ORIGINAL PRICE	NEGOTIATED PRICE	ORIGINAL AMOUNT	NEGOTIATED PRICE	ORIGINAL AMOUNT	NEGOTIATED AMOUNT
1	Bitzer compressor rewinding work Removing of compressor stator, old wire, varnishing, baking till the desired temperature of copper winding.	Nos	2	2,450.00	2,275.00	4,900.00	4,550.00	2,400.00	2,300.00	4,800.00	4,600.00	2,400.00	2,300.00
						TOTAL	4,900.00	4,550.00		4,800.00	4,600.00		4,800.00

Selection Criteria  
Better Quality

Lowest Bidder   
Reputed Supplier

**Objective of purchase/service;** Bitzer compressor needs to rewinding at GUC cold store, the winding is fully damaged due to mechanical components getting stuck and humidity. The maintenance report is attached for reference.  
Recommended by GUC cold store maintenance team.

RECOMMENDED VENDOR		NEGOTIATED AMOUNT (QAR)	PAYMENT TERMS
VENDOR NAME	ORIGINAL AMOUNT (QAR)		
GULF TEAM TRADING	4,900.00	4,550.00	100% AGAINST INVOICE

  
  
  
Approved by \_\_\_\_\_  
Checked by \_\_\_\_\_  
Prepared by \_\_\_\_\_