

Document Details							
Parked by	AHMED 2433002497	Posted by	SHAMEER 5301	Fiscal Year	2024		
Doc. Number	28.07.2024	Company Code		Period	11		
Doc. Date		Calculate Tax					
Ref. Doc.		IN-HED-100626					
Doc. Currency	QAR						

Date	Debit	Credit	Description	Amount	Amount	Date	Debit	Credit	Description	Amount	Amount
31/07/2024	20300695	MANNAI TRADING COMPA Y VS P.MACHINE EQUIP	24330024972024	9,851.00	-	31/07/2024	20300695	9,851.00	Material and Labour Charge	9,851.00	-
31/07/2024	20300695	MANNAI TRADING COMPA Y VS P.MACHINE EQUIP	24330024972024	9,851.00	-	31/07/2024	20300695	9,851.00	Material and Labour Charge	9,851.00	-

S.

HB

MANNAI TRADING CO. W.L.L.
 P.O.Box: 76 Doha, Qatar
 Telephone: 44558888/44076000
 Heavy Equipment Division - Service



شركة المناعي التجارية ذ.م.م

ص.ب: 76، الدوحة، قطر

تلفون: 44076000 / 44558888

قسم المعدات الثقيلة - الخدمة

Original

أصل

INVOICE

الفاتورة

(Credit Invoice)

2433002499

Customer Name : ALCAT CONTRACTING CO.
 اسم العميل
 Customer Number : 5956
 رقم العميل
 Contact No :
 رقم الاتصال
 LPO reference No : 5530102655
 رقم أمر الشراء
 Job Type : Credit Customer
 نوع العميل
 Customer Address : DOHA, QATAR,,
 ملوان العميل
 Make : JCB 456ZX WHEELED LOADER
 Model : JCB 456ZX WHEELED LOADER
 Reg.No : 57605 CHASSIS NO: JCB456Z0H02061182 رقم القاعدة رقم لودة التسجيل

Invoice Number : IN-HED-100626

رقم الفاتورة

Invoice Date : 28-JUL-24

تاريخ الفاتورة

Jobcard No : 09104770

رقم أمر الشغل

Account No : 2176040

رقم الحساب

S.No	Description	Total Price	Disc %	Disc Value	Amount (QAR)
رقم	بيان	السعر الإجمالي	نسبة الخصم	قيمة الخصم	المبلغ بالريال القطري
1	Material and Labour Charges و تكلفة قطع الغيار / الخامات المصنوعيات	9,851.00	0.00	0.00	9,851.00
<u>Jobs Carried Out</u>	Total : الإجمالي	9,851.00		0.00	9,851.00

CHECKED AND REPAIR BRAKE SYSTEM NOT WORKING IN JCB 456ZX WHEELED LOADER REG#57605 AS PER HED/Q/VKP/324RR/2024

الاعمال التي اكملت

(Qatar Riyal Nine Thousand Eight Hundred Fifty One Only.)

ق.ر فقط تسعة آلاف وثمانمائة وواحد وخمسون .

Please Retain this Receipt

1. If you have any question concerning this invoice, contact Department Quoting this Invoice Number.

يرجى الاحتفاظ بهذه الاصل
إذا كان لديكم أي استفسار بخصوص هذه الفاتورة، يرجى الاتصال بالإدارة مع الإشارة لرقم هذه الفاتورة.



Acknowledgement

الاقرار

Received By :

تم الاستلام بواسطة

Name :

اسم

Signature :

التوقيع

Date :

Time

التاريخ

19-NOV-24 08:27 AM

Wheel loader
Ref N°. 57605
Fawzy

For:

19-11-24

Prepared By

Bishu

Authorized By

Magdy Fawzy

Page 1 of 1

Pay by Account Payee Cheque in favour of Mannai Trading Company or by Wire Transfer to Mannai Trading Company

A/C No. QAR-0108025060011 (IBAN No. QA35QISB00000000108025060011), SWIFT-QISBQAQAXXX, Qatar Islamic Bank, PO BOX 559, DOHA-QATAR

Registered in Qatar with Limited Liability, Commercial Registration No. 8191, Authorised and paid up capital QR 50,000,000

الدفع عن طريق شيك لحساب المستفيد لمصالح شركة المناعي التجارية أو عن طريق التحويل المصرفي لشركة المناعي التجارية

A/C No. QAR-0108025060011 (IBAN No. QA35QISB00000000108025060011), SWIFT-QISBQAQAXXX, Qatar Islamic Bank, PO BOX 559, DOHA-QATAR

مسجلة في قطر ذات مسؤولية محدودة ، سجل تجاري رقم 8191 ، برأس مال مدفوع 50000000 رق

Field Service Repair Record

Job No.:	Date:	Customer Name: <i>MANNAI CORPORATION</i>		
Equipment Make / Manufacturer:		Site Address: <i>STAGE 10</i>		
Machine Model:	Serial No.:	Contact Name: <i>ABDULKAREEM</i>		
Registration No. / Chassis No.:	Engine Model:	Contact Number: <i>5014918</i>		
2nd Engine:	Engine Serial:	Complaint / Job Details As Described By the Customer:		
Date in Service				
Hr. Sup:	Hr. Carr:	Km:	<i>Brake Failure</i>	
Travel To Site @	Arrive @	Customer Signature:		Date: 10/11/2018
Findings / Observations:		Clock ON	Clock OFF	Time
<i>Brake failure.</i> <i>Brake pad free on the road</i> <i>Brake, the brake was functioning.</i> <i>Brake lever missing no master</i> <i>Brake pads the brake pedal.</i>				
Trouble shooting:		<i>checked the brake system pressure</i> <i>at 17 barad 165 and 17 equal to 200</i> <i>then press the brake pedal and showing</i> <i>the brake warning and park brake engaged</i> <i>checked the both brake accumulator and found</i>		
Corrective Action:		<i>found oil coming through the gas pressure side</i> <i>Brake accumulator failed condition => Need to replace</i> <i>need to check the brake system operation after replacement</i> <i>then went to workshop and with the help of technician</i> <i>(downloaded)</i>		
Comments:		<i>will wear harness locally repaired by customer</i> <i>need to improve the safety harness.</i>		

This is to certify that the work has been carried out & the equipment is operating satisfactorily

Technician: *J. K. S.*Date: *10/11/2018*Customer or Agent Signature: *MANNAI CORPORATION*Date: *10/11/2018*Representative Signature: *J. K. S.*Date: *10/11/2018*



No 28651

Field Service Repair Record

Job No.:	Date:	Customer Name:
Equipment Make / Manufacturer:	Site Address:	
Machine Model: 786 2A	Serial No.: 57605	Contact Name: ABHISHEK
Registration No. / Chassis No.: 2061182	Contact Number:	
Engine Model:	Engine Serial:	Complaint / Job Details As Described By the Customer:
2nd Engine:	Repairs as per job	
Date in Service	18/07/2014	
Hr. Sup:	Hr. Carr: 25 162	Km:
Travel To Site @ 1699289	Arrive @	Customer Signature: Date: 18/07/14
Findings / Observations: Came out the pump as per specification HSD (Oil pump) 240 R 124. 1) Replaced the both pump assembly with new one. 2) Filled nitrogen gas on the accumulator. 3) Started the unit and checked the operation and pressure (169 Bar). System operation found good. After the accumulator installation checked pressure holding efficiency found poor. (Retained the customer to replace pump.)		Clock ON Clock OFF Time
Troubleshooting: as per pump pump replacement.		
Corrective Action: Replaced pump and found the pressure holding efficiency found poor. (Retained the customer to replace pump.)		
Comments:		

This is to certify that the work has been carried out & the equipment is operating satisfactorily

Technician:

Date:

Customer or Agent Signature

Date:

Representative Signature:

Date:



SUBARU



GROVE



TCM

Allison Transmission

ELGIN



EICHER



CompAir