



PROFORMA INVOICE

Page 01

Customer	QATAR FLOUR MILLS CO.	Date	07.08.2024
Cust ID	QP38020	Invoice No	WOIQT59577-02
Address	P.O.BOX 1444 Doha Qatar	PO Number	LPO#5500203206
		Job No	QT59577
		Model No	C9 SR No OJSC16609

1000013310

Sr. No.	Description	Unit	TOTAL
1	TRAVEL TO/FROM WORK AREA		
2	PERFORM TA1 INSPECTION		
3	REMOVE & INSTALL VALVE COVER		
4	REMOVE & INSTALL 6 UNIT INJECTOR		
5	CALIBRATE 6 UNIT INJECTOR		
6	REMOVE & INSTALL WATER TEMP REGULATOR H		
7	REMOVE & INSTALL TURBOCHARGER		
8	REMOVE & INSTALL UNIT INJECTOR WIH		
9	PERFORM 2000 SVC HOUR MAINTENANCE		
10	DRAIN & REFILL ENGINE COOLANT		
<i>50387195 D</i>			LUMP SUM AMOUNT
			60,988.80
			PAYMENT RECEIVED
			BALANCE PAYMENT AFTER CORE REFUND
			30,494.00
			21,938.80
TOTAL QAR: Twenty one thousand nine hundred thirty eight and 80/100 only			QAR : 21,938.80


Customer Signature

For Mohamed Abdulrahman Al-Bahar & Sons W.L.L

Mohamed Abdulrahman Al-Bahar & Sons W.L.L.
P.O.Box 2171, DOHA-QATAR

Abdulatif A. Elmoujawaz
Machine Section Manager

Selvaraj Mysamy
Service Manager



MOHAMED ABDULRAHMAN AL-BAHAR & SONS W.L.L.
P.O Box 2171, Doha, Qatar
Tel. +974-40159656
Fax +974-44600225
Web: www.albahar.com

محمد عبد الرحمن البحار وأولاده ل.م.م

منصب: ٢١٧١، الدوحة - قطر

تلفون: +974-40159656

fax: +974-44600225

موقع إنترنت: www.albahar.com



محمد عبد الرحمن البهار وأولاده د.م.م
MOHAMED ABDULRAHMAN AL-BAHAR & SONS W.L.L.

FIELD SERVICE REPORT



DATE 02 - 08 - 2023

BRANCH DOHA

DEALER CODE Q847 Report #

CUSTOMER	
NAME	Peter Elouer Mihel
NUMBER	
JOB SITE	Doha
CONT. PRSN	
POSITION	
TEL. No.	

MACHINE / ENGINE	
MAKE	CAT
MODEL	C9
SER. No.	JSC16609
ARRNGNT. No.	
O.T.SPECS	
SMU'S (HR'S)	11140

WORK OEDER	
WORK ORDER No.	PT-SG 577
PIP No.	
WARRANTY INDICATOR	<input type="radio"/> YES <input type="radio"/> NO
OVERTIME CHARGEABLE	<input type="radio"/> YES <input type="radio"/> NO

EMPLOYEE NAME	NO.	LABOUR CODE
Jayansha	148	98

VEHICLE	
PLATE No.	120407
KM's-START	187811
KM's END	
TOTAL KM's	

SEG	FROM	TO	DURATION
01 T/START	5-00	6-00	TR1
02	6-00	13-00	7:00
03	14-00	16-30	2:30
04			
01 T/END			
TOTAL HOURS	REG	O/T	TOTAL

CUSTOMER COMPLAINT

Engine loss Power.

PROBLEM FOUND

PROBLEM CAUSE (S)

HOW WAS THE PROBLEM CORRECTED - SUGGESTIONS TO AVOID OCCURRENCE AGAIN

- Remove Valve cover and Injectors.
- Replace worn Injectors. Do the trim calibration.
- Replace Injector borehole.
- Performed Valve leak.
- idle idle oil and cooler.

OTHER ITEMS NEED ATTENTION

Start and check engine with operator found all ok

Need to be replace Radiator cap.

QUOTE	PSSR	W/O	NEXT TIME

JOB COMPLETED: YES NO

MACHINE / ENGINE TO BE BROUGHT INTO THE WORKSHOP: YES NO

FURTHER ACTION REQUIRED :

UNUSED PARTS RETURNED: YES NO

SUPERVISOR SIGN.:

SERVICEMAN SIGN.:

DATE: 02-08-2024

FOR CUSTOMER USE : TIME SERVICEMAN ARRIVED ON SITE : TIME SERVICEMAN LEFT SITE :

COMMENTS / FURTHER REQUIREMENTS :

CUSTOMER REP.: MOJYAB POSITION: SIGN: A.B.K DATE: 2-8-24

FOR CUSTOMER INTERNAL USE : (To be used by the customer after receiving the report, for his internal comments, notes,etc)

work completed.



مohamed abdulrahman al-bahar & sons wll

FIELD SERVICE REPORT



DATE 01 - 08 - 2024

BRANCH CATERPILLAR

DEALER CODE CP303 Report #

CUSTOMER	
NAME	Paper flour mill
NUMBER	
JOB SITE	Doha
CONT. PRSN	
POSITION	
TEL. No.	

MACHINE / ENGINE	
MAKE	CAT
MODEL	CG
SER. No.	JSC16609
ARRNGNT. No.	
O.T.SPECS	
SMU'S (HR'S)	11140

EMPLOYEE NAME	NO.	LABOUR CODE
Jayawha	148	PP

VEHICLE	
PLATE No.	120407
KM's-START	187742
KM's END	187811
TOTAL KM's	

SEG	FROM	TO	DURATION
01 T/START	9-00	10-00	TR-1
02	10-00	11-00	TA-1
03	11-00	13-00	28M
04	14-00	18-30	48D
Q1 T/END			
TOTAL HOURS	REG	O/T	TOTAL

CUSTOMER COMPLAINT

Engine low Power-

PROBLEM FOUND

PROBLEM CAUSE (S)

HOW WAS THE PROBLEM CORRECTED - SUGGESTIONS TO AVOID OCCURRENCE AGAIN

Remove and Replace the Turbo chaper
 Drain the coolants
 Remove and Replace water Regulator
 Change fuel filter
 Change oil and oil filters.

OTHER ITEMS NEED ATTENTION

QUOTE	PSSR	W/O	NEXT TIME

JOB COMPLETED: YES NO MACHINE / ENGINE TO BE BROUGHT INTO THE WORKSHOP: YES NO

FURTHER ACTION REQUIRED :

UNUSED PARTS RETURNED: YES NO

SUPERVISOR SIGN. :

SERVICEMAN SIGN. :

Jad

DATE: 01-08-2024

FOR CUSTOMER USE : TIME SERVICEMAN ARRIVED ON SITE : TIME SERVICEMAN LEFT SITE :

COMMENTS / FURTHER REQUIREMENTS :

CUSTOMER REP: *Mohamed Al-Bahr* POSITION: SIGN: *ABK* DATE: 2-8-2024

FOR CUSTOMER INTERNAL USE : (To be used by the customer after receiving the report, for his internal comments, notes,etc)

SERVICE MEMORANDUM

QFMSM/2024/029

Date : 20-April-2024

		BASIC DETAILS OF SERVICE/MEMO			
Nature Service	Service Description	SUPPLIER DETAILS		PURCHASE DETAILS	
Department	Maintenance	Supplier name	Mohamed Abdulrahman Al-Bahar Co-Qatar	Total value of SM	QAR 56,225.72 Rate per month :-
Service Type	Renewal <input type="checkbox"/> or New Service <input checked="" type="checkbox"/>	Contract period	one time	Service Memo.	QFMSM/2024/029 Date : 01.11.2020

REASON/OBJECTIVES OF THIS PURCHASE

1-One of the Vigan machine Engine (Tripper Vehicle) (S/N No. OSC46609) is under break-down at present, due to smoke issue and oil passing from Engine to clutch side and the bunker operation is going on with only one Vigan machine.

Brief summary/ Justification of Both Vigan machines which are used to load wheat in Trippers from Bunkers

a-Both Vigan machines are more than 12 years old and till date there is no major overhauling done on these Engines

b-In 2019 we had called service agent of Caterpillar Engines to check the condition as smoke was coming and then the injectors were replaced for both engines.

c-Now again we got both Engines checked by the service provider and the report is attached where we need to change injectors, Turbocharger and few more items to restore the Engine which is out of order

d-The other Engine, which is in use also requires the same work and will be done to avoid breakdown but will initiate it later on once we restore the breakdown Engine back

2-Warranty: 1 year for spare parts and 3 months on labour+workmanship only.

3-The quoted prices are exclusive of any taxes. In case of introduction of tax by the authorities, the same will be applicable and paid by us separately.

4-After dismantling, any additional spares required, same will be quoted separately and paid at actual.

5-Please refer to quotation no.QT59377-001 attached for detailed scope, terms and conditions.

6-Remain inspection charges are refundable (QAR 8,556/-) subject to acceptance of core as per the caterpillar core criteria. If accepted, it will be credited from the total cost of QAR 60,988.80/-

7-E-mail is attached for discount and payment term from supplier.

No other comparison is available as Mohamed Abdulrahman Al-Bahar is Authorised Service provider for CAT Engine in Qatar.

No	Supplier Name	Service Description	Currency	Quoted Amount	QUOTES SERVICE PROVIDER DETAILS		Payment Terms
					Negotiated Amount	Exchange rate	
1	Mohamed Abdulrahman Al-Bahar & Sons W.L.L (CAT)	Engine repair of Vigan Machine	QAR	60,988.80	60,988.80	1.00	- Total - Qar. 60,988.80 50% CDC & 50% PDC without BG Total QAR 60,988.80

* All the supported documents are attached herewith

Particulars	Supplier Name	Negotiated Amount	Exchange rate	Amount in FC	Service Period in days	Total - Qar.	RECOMMENDED SERVICE PROVIDER DETAILS		Payment Terms
							<input checked="" type="checkbox"/> Others (Specify)	<input checked="" type="checkbox"/> Authorised Service provider of CAT engine in Qatar	
Budgeted value for the requested service/expense				150,000					
Budget utilized till last purchase				-					
Balance available for this purchase					150,000				
Proposed as per this service memorandum					(60,988)				
Surplus/(deficit)					89,011				

INFORMATION APPROVAL

Vishnu Prasad	Abdul Aziz	Tayyib Mohammad Aslam	Fahim Rasmy	Hamed Bushra	Adnan Moerji	Asst. Vice President - Finance	Sunil Kasmin
Senior Officer - Procurement	Senior Manager - Maintenance	Senior Manager - Procurement	Senior Manager - Finance	General Manager	General Manager	26/05/2024	28/05/2024

PURCHASE ORDER

Qatar Flour Mills Co.

PO Box: 1444, Al Meena Street

Doha Qatar

Email: Tel:44415000 Fax: 44438137



PURCHASE ORDER DETAILS

PO No.	5500203206	PO Date	28/05/2024
PO Amend No.	Amend Date		
PO Status	Open	Type	General
Project Code	Offer No		
Project Name	Pur Group 139-NONE		

TERMS & CONDITIONS

SUPPLIER DETAILS	
Supplier Name	MOHAMED ABDULRAHMAN AL-BAHAR & SONS
Supplier Code	20300058
Contact Person	Contact Address P.O.BOX 2171,DOHA,,
Tel No.	40159555
Fax	44600225
Mobile	55576449
Email	

ITEM DETAILS

S.No	PO Line	Item Code and Description	Sh.No	Need Date	UOM	Quantity	Unit Rate	Value
1.1	00010	550000207 - REPAIRING OF VIGAN MACHINE ENGINE	0000	28/06/2024	EA	1.00	60,988.80	60,988.80
Gross Price								60,988.80
Grand Total								60,988.80

Amount in Words: Qatari Riyal Sixty Thousand Nine Hundred Eighty-Eight and Eighty dirham Only

For Qatar Flour Mills Co.

Delivery Address : Qatar Flour Mills Co.

(Authorized Signatory)

Document Level Note :

QFM-SM-2024-029

Created by: Vishnu Prasad

Approved By: Adnan Meerji