

# TECHNICAL SERVICE REPORT

Report Number	554655/TSR-S023/VIII/2016	Type of Vehicle	XENIA X STD NEW 1.3 4X2 MT B 2013	Cont. Year	2013
Report Date	2016-08-12	Police Number	BG1605ID	Kilometer	185.500
Branch	Leasing Palembang	<b>Engine Number</b>	MB71456	Warranty Claim	O Yes  ● No
Mechanic Name	ADI.S	<b>Chassis Number</b>	MHKVBA1JDK025347	Insurance Claim	O Yes  ● No
<b>Driver Name</b>	KEMLI	Trouble	SUSAH MASUK GIGI	Backcharge	O Yes O No

CUSTOMER NAME	USER NAME	LOCATION / SITE	OPERATIONAL CONDITION
SUMATERA PRIMA FIBREBOARD	KEMLI	SUMSEL	<b>⊚</b> CITY OPLANTATION OMINING OFORESTRY

## **Chronology of Even:**

> Pada saat di lakukan pemeriksaan dan perbaikan oleh mekanik di temukan keausan pada Disc Clutch.

#### **Historical Maintenance:**

> P. Rutin BG1605ID Km.165.089.Oh clutch ( 17.05.2016 )

## **Analysis:**

> Dari hasil pengecekan terdapat keausan pada clutch.( sering nekan clutch gantung )

## PICTURE OF WRECK COMPONENT



No.	Component	Price
1	clutch assy	1.220.000
	Total Cost	1.220.000

CAUSES OF TROUBLE	JOB DESCRIPTION	REPORT DISTRIBUTION
O MIS DIS/ASSEMBLY	MAINTENANCE	☑ FLEET DEPT.
O MIS HANDLED	O REPAIR	□ CUSTOMER
	O OVERHOULE	□ CORP. FLEET (HO)
O LIFE TIME	O BODY REPAIR	□ VENDOR
O MATERIAL DEFECT	O RECONDITION	□ ATPM

FOREMAN	SA MAINTENANCE	FLEET HEAD/CO.	ADM. HEAD	BRANCH MANAGER	FLEET SUPPORT	CORP.FLEET DIV.HEAD
Usman	Tabrani	Jumadi	Deni Shapta Hardiansyah	Harun Setiawan	Suwandi	Sofyan Haji