MSTL - 002 INDUSTRIAL STATISTICS LAB

- Session 1: Control Charts for Mean
- Session 2: Control Charts for Mean using Range
- Session 3: Control Charts for Mean using Standard Deviation
- Session 4: Control Charts for Range
- Session 5: Control Charts for Standard Deviation
- **Session 6:** Control Charts for Fraction Defective
- Session 7: Control Charts for Fraction Defective with Variable Sample Size
- **Session 8:** Control Charts for Number of Defectives
- Session 9: Control Charts for Number of Defects
- Session 10: Control Charts for Number of Defects per Unit
- **Session 11:** Simple Linear Regression
- Session 12: Multiple Linear Regression
- **Session 13:** Regression with Dummy Variable
- Session 14: Variable Selection Methods
- **Session 15:** Estimation of Trend by Curve Fitting
- **Session 16:** Smoothing or Filtering the Time Series
- **Session 17:** Seasonal Component Analysis