

```
int en1 = 5;

int in1 = 2;

int in2 = 3;

int potPin = A0; // Potentiometer

int potValue;

int motorSpeed;


void setup()
{
    pinMode(en1, OUTPUT);
    pinMode(in1, OUTPUT);
    pinMode(in2, OUTPUT);
    pinMode(potPin, INPUT);


    digitalWrite(in1, HIGH);
    digitalWrite(in2, LOW);
}


void loop()
{
    potValue = analogRead(potPin);
    motorSpeed = map(potValue, 0, 1023, 0, 255);


    // Control motor speed
    analogWrite(en1, motorSpeed);
}
```

