FAST integrator (gain = 0.1): closed-loop step response 0.10 Input disturbance (unit step) Closed loop response 0.08 Tip position (DM units) 0.06 0.04 0.02 0.00 0.2 0.0 0.4 0.6 8.0 1.0 Time (s)