Scrutineer Evidence Pack — BBW 2.3 — 2026-11-09 11:32 UTC

By scrutineer · a minute ago · Listen

GO **Release BBW 2.3 is GO** — readiness 100/100, 0 blocking finding(s).

Scope and profile

Project **BBW**, release **BBW 2.3**, profile ISO 26262. 14 safety requirements, 5 ASIL-rated hazards, 16 verifying test cases. Generated by Aditya Gupta at 2026-11-09 11:32 UTC.

Traceability matrix

Safety requirement	ASIL	Hazards mitigated	Implementation	Verification (latest result o BBW 2.3)
REQ **BBW-27** Brake pedal position sensor plausibility check	D	HAZ **BBW-1** HAZ **BBW-2**	IMP **BBW-42** (Done)	TC **BBW-72**: Passed (simulated HIL bench, 2026-11-09)
REQ **BBW-28** Dual-channel pedal sensor acquisition with	D	HAZ **BBW-1**	IMP **BBW-43** (Done)	TC **BBW-56**: Passed (CI (HIL pipeline #1180) — https://ci.exam

				TC **BBW-70**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-05
REQ **BBW-29** Brake command timeout handling	D	HAZ **BBW-1**	IMP **BBW-44** (Done)	TC **BBW-57**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-04
REQ **BBW-30** Wheel-speed sensor redundancy cross-check	D	HAZ **BBW-1** HAZ **BBW-3**	IMP **BBW-45** (Done)	TC **BBW-58**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-05
REQ **BBW-31** Redundant brake actuator command path	D	HAZ **BBW-1**	IMP **BBW-46** (Done)	TC **BBW-59**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-03
REQ **BBW-32** Unintended	D	HAZ **BBW-2**	IMP **BBW-47** (Done)	TC **BBW-60**: Passed (CI (HIL pipeline

				ple.com/hil/118 0, 2026-11-04 TC **BBW-61**: Passed (CI (HIL pipeline #1180) — https://ci.exam ple.com/hil/118 0, 2026-11-05
REQ **BBW-33** Brake force distribution limit per axle	C	HAZ **BBW-3**	IMP **BBW-48** (Done)	TC **BBW-62**: Passed (CI (HIL pipeline #1180) — https://ci.exam ple.com/hil/118 0, 2026-11-03
REQ **BBW-34** Yaw-rate monitored brake balancing	C	HAZ **BBW-3**	IMP **BBW-49** (Done)	TC **BBW-63**: Passed (CI (HIL pipeline #1180) — https://ci.exam ple.com/hil/118 0, 2026-11-04
REQ **BBW-35** End-to-end brake latency ≤ 150 ms	B	HAZ **BBW-4**	IMP **BBW-50** (Done)	TC **BBW-64**: Passed (CI (HIL pipeline #1180) — https://ci.exam ple.com/hil/118 0, 2026-11-05

CAN brake message end-to-end protection			(Done)	Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-03
REQ **BBW-37** Brake lamp activation within 100 ms	A	HAZ **BBW-5**	IMP **BBW-52** (Done)	TC **BBW-66**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-04
REQ **BBW-38** Brake lamp output short-circuit diagnosis	A	HAZ **BBW-5**	IMP **BBW-53** (Done)	TC **BBW-67**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-05
REQ **BBW-39** Safe-state entry logging to non-volatile memory	B	—	IMP **BBW-54** (Done)	TC **BBW-68**: Passed (CI (HIL pipeline #1180) — https://ci.example.com/hil/1180, 2026-11-03
REQ **BBW-40** Degraded-mode driver warning within	B	HAZ **BBW-4**	IMP **BBW-55** (Done)	TC **BBW-69**: Passed (CI (HIL pipeline #1180) —

No findings. Every rule in the profile passed.

Suspect-link history (change impact)

Test	Upstream change	Resolution
TC **BBW-58**	upstream REQ BBW-30 changed (description) — Marta Kowalski, 2026-11-06	Impact review by Aditya Gupta on 2026-11-09: “demo justify”

Sign-off

Role	Name	Signed
Safety Manager	Aditya Gupta	2026-11-09 11:32 UTC
Test Lead		
Release Manager		

Integrity

SHA-256 of the evaluated snapshot:
`5a74827b0a37b0bf48ed85a1e27ace3489c74ef27cf29bd28aa135242c5a32f5`
Snapshot id: `BBW:BBW 2.3:2026-11-09T11:32:47.089Z`. Scrutineer stores this snapshot. Re-computing the hash verifies that this page matches the evidence it was generated from.

Scrutineer supports evidence gathering. It does not certify compliance.