


Lower confidence + greater uncertainty



PHASE 11 CONTROLLED EXPERIMENT

Conf.	Risk	Envelope	State / speed
0.95	0.551	2.19x	CAUTIOUS / 0.65
0.80	0.578	2.24x	CAUTIOUS / 0.65
0.60	0.625	2.33x	CAUTIOUS / 0.65
0.40	0.683	2.43x	CAUTIOUS / 0.65

Same pedestrian geometry; confidence and measurement uncertainty vary together.
Risk and envelope grow; the state remains CAUTIOUS and speed scale remains 0.65.
No artificial STOP transition is added.