Calibration board: 10x7 squares (9x6 inner corners), 25 mm squares. Print at 100%. Tape FLAT on stiff board.

