

| Date: 25/May/2022 | Product family: |
|----------------------------------|-----------------|
| Subject: Printerset release note | |

Firmware last available revision:

| | DATE | RELEASE NOTES |
|------|-------------|---|
| | DAIL | Fixed Load TrueType font routine Added support of new Optional Features Fixed Ethernet devices enumeration Fixed error with programming modules Added "/WRITEONLYDIFF" and "/DISRESETANOOP"; into the command line Added "/NALLOWDGRADE" to disallow the downgrade Added "/NALLOWEQGRADE" to disallow the upgrade if equal Added "/UPGDESCR" to select the fields of pfw file to upgrade |
| | | Fixed the Log path (from command line) and output file name Fixed error in Font editor window |
| 3.82 | 25/May/2022 | Fixed error in loading parameters due to short timeout. |
| 3.68 | 02/May/2021 | Bug fixed for "Scan paper from device" feature in "Blackmark" area: inserted a different image error management |
| 3.67 | 08/Mar/2021 | Fix the close of the ethernet communication Remove the save of the "C:\\Mod.bin" file during the load of a module Add the support, into the upgrade, of the error 0x98 returned when the upgrade port is not supported Fixed read timeout for Bluetooth module Encrypted the password strings into the PSC file Added to Blackmark_Scan_Distance parameter the 700 mm value and changed default start value from 80 mm to 250 mm |
| 3.62 | 10/Nov/2020 | Removed upgrade lock between different AERO firmware versions Fixed stock control cut position setting |
| 3.57 | 10/Jan/2020 | Changed button Check "Module Font" to "Module File Info" Added support for fonts rotated 90° Added support to edit fonts from PFW file Added new upgrade procedure Improved Ethernet communication Improved Virtual COM communication Fixed error in loading old PSC files |
| 3.45 | 31/Jul/2019 | Added Item tooltip with default parameter value Added selection of parameter group to reset with Factory Default button Added printer name in COM port list if Virtual COM Fixed bug with Tool tab Fix with Ethernet device discovery |
| 3.35 | 05/Dec/2018 | Added Optional Features Tab Added scanner command line upgrade support Added camera module support for Multiscan Added visual notification for error in parameter values Fix description for Retract parameter |
| 3.28 | 14/May/2018 | Added Advanced Blackmark and Stock Control tab for KPM862 Added new upgrade type Various fixes for PSC and CFN file management Added Security key support Added logo MOD support |

World Headquarters





| 3.06 | 07/Aug/2017 | Redesigned UI and name changed to Printerset Added Upload Script File tool for PP54 Fixed command line bug Added copy and paste of multiple characters from CFN to MOD file Improved Logo editor Added video tutorial Added True Type fonts management tab |
|------|-------------|--|
| 2.71 | 29/Jun/2016 | Added Logo copy to clipboard Added upgrade type U4 |
| 2.58 | 25/Jan/2016 | Fixed upgrade bug with PFW files |
| 2.56 | 18/Jan/2016 | Added Status tab Various fixes for Font editor Added MOD file editing without communicating with the device Added Date and Time setting tool Fixed error in logo save Fixed bug in Ethernet upgrade procedure |
| 2.35 | 32/Feb/2015 | Added CFN file management |
| 2.25 | 18/Dec/2014 | Added device Font editor tab |
| 2.23 | 18/Jun/2014 | Various improvements on communication with the device Fixed PSC file load |
| 2.12 | 07/May/2014 | Improved list of fonts UI Added Logo management tab Added Tools tab Added Ethernet port support |
| 2.06 | 13/Jul/2013 | Added support for MOD files Added printhead dot test result Added Export to txt file all printer settings |
| 2.00 | 11/Dec/2012 | First release |

Additional Notes:

World Headquarters

CUSTOM S.p.A. Via Berettine, 2/B - 43010 Fontevivo Parma ITALY / Tel. +39 0521 680111 - Fax +39 0521 610701 VAT: IT02498250345 Cap. Soc.: 6.000.000 € I.V. / Reg. Imprese Parma n. IT02498250345 / REA n. 243435

