


WINDOW LIGHTS

R Y R
MAY 15/18

33-21-00
SECTION TITLE
PAGE 1

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG



3 33215171 SHT 1 REV 022



LIGHT INSTL-LED SIDEWALL FWD LH
FIGURE 71 (SHEET 1)

33-21-51-71

RJR
JUL 15/18

33-21-51-71
PAGE 0

ECCN 9E991 BOEING PROPRIETARY - See title page for details.



3 33215171 SHT 2 REV 012

LIGHT INSTL-LED SIDEWALL FWD LH
FIGURE 71 (SHEET 2)

33-21-51-71

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
71			LIGHT INSTL-LED SIDEWALL FWD LH		
- 1	MODREF702610		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5504-41001 REV A POSITION DATA: FWD LH	001037	RF
- 1	MODREF828046		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5504-41001 REV B POSITION DATA: FWD LH	038999	RF
6	BACS12ER3K10		.SCREW		3
7	BACS12FA3K5		.SCREW		8
9	69-66047-1		.WASHER-RTNR		6
10	71320-04		.RETAINER-LENS SUPPLIER CODE: V59579		1
15	71320-08		.RETAINER-LENS SUPPLIER CODE: V59579		2
20	6047-012		.LENS- SUPPLIER CODE: V59579		1
25	6047-028		.LENS- SUPPLIER CODE: V59579		1
30	6047-061		.LENS- SUPPLIER CODE: V59579		1
33	417A5464-49		.SHIELD		3
35	PLT1-5IM		.STRAP SUPPLIER CODE: V06383 SPECIFICATION NUMBER: BACS38K5 OPTIONAL PART: T03R0 V53421		AR
40	417N5107-2		.GROMMET		1
45	71289-00		.BRACKET ASSY- SUPPLIER CODE: V59579 MISCELLANEOUS DATA: Q659A4791-3 IS BOEING PREFERRED SPARE PART.		2
45	71289LS01-00		.BRACKET ASSY- SUPPLIER CODE: V59579		2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-51-71

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
 FIG. 71
 PAGE 1
 NOV 15/20

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
71					
45	Q659A4791-3		.BRACKET ASSY-		2
50	417A5464-31		.HOOK-WIRE SPRT		6
55	9651-14-0004		.LIGHT ASSY-14 IN. TYPE E CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE E CONN 14" ELECTRICAL EQUIP NUMBER: M02800 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-02		1
130	9651-35-0005		.LIGHT ASSY-35 IN. TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 35" ELECTRICAL EQUIP NUMBER: M02799 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-06		1
200	9651-35-0001		.LIGHT ASSY-35 IN. TYPE B CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE B CONN 35" ELECTRICAL EQUIP NUMBER: M02818 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-05		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					


— ITEM NOT ILLUSTRATED

RYR



33-21-51-71

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51
FIG. 71
PAGE 2
NOV 15/20



33-21-51-71A
PAGE 0



3 33215171A SHT 2 REV 012

LIGHT INSTL-LED SIDEWALL FWD RH
FIGURE 71A (SHEET 2)

33-21-51-71A

RJR
JUL 15/18

33-21-51-71A
PAGE 0A

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
71A			LIGHT INSTL-LED SIDEWALL FWD RH		
- 1	MODREF702615		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5504-42007 REV A POSITION DATA: FWD RH	001037	RF
- 1	MODREF828055		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5504-42007 REV B POSITION DATA: FWD RH	038999	RF
5	BACS12ER3K10		.SCREW		3
10	BACS12FA3K5		.SCREW		8
12	69-66047-1		.WASHER-RTNR		6
15	71320-05		.RETAINER-LENS SUPPLIER CODE: V59579		1
20	71320-08		.RETAINER-LENS SUPPLIER CODE: V59579		2
25	6047-012		.LENS- SUPPLIER CODE: V59579		1
30	6047-028		.LENS- SUPPLIER CODE: V59579		1
35	6047-064		.LENS- SUPPLIER CODE: V59579		1
37	417A5464-49		.SHIELD		3
40	PLT1-5IM		.STRAP SUPPLIER CODE: V06383 SPECIFICATION NUMBER: BACS38K5 OPTIONAL PART: T03R0 V53421		AR
45	417N5107-2		.GROMMET		1
50	71289-00		.BRACKET ASSY- SUPPLIER CODE: V59579 MISCELLANEOUS DATA: Q659A4791-3 IS BOEING PREFERRED SPARE PART.		2
50	71289LS01-00		.BRACKET ASSY- SUPPLIER CODE: V59579		2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-51-71A

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
 FIG. 71A
 PAGE 1
 NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
71A					
50	Q659A4791-3		.BRACKET ASSY-		2
55	417A5464-31		.HOOK-WIRE SPRT		6
60	9651-14-0004		.LIGHT ASSY-14 IN. TYPE E CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE E CONN 14" ELECTRICAL EQUIP NUMBER: M02800 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-02		1
130	9651-35-0005		.LIGHT ASSY-35 IN. TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 35" ELECTRICAL EQUIP NUMBER: M02799 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-06		1
200	9651-35-0001		.LIGHT ASSY-35 IN. TYPE B CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE B CONN 35" ELECTRICAL EQUIP NUMBER: M02818 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-05		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED


RYR

33-21-51-71A

ECCN 9E991 BOEING PROPRIETARY — See title page for details.

33-21-51
 FIG. 71A
 PAGE 2
 NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG



3 33215174 SHT 1 REV 011


LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 1)

33-21-51-74

RJR
JUL 15/18


33-21-51-74
PAGE 0

ECCN 9E991 BOEING PROPRIETARY – See title page for details.



LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 2)


33-21-51-74



3 33215174 SHT 3 REV 022

LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 3)

33-21-51-74




3 33215174 SHT 4 REV 022

LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 4)

33-21-51-74

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG



3 33215174 SHT 5 REV 022





LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 5)

33-21-51-74

RJR
JUL 15/18

33-21-51-74
PAGE 00


ECCN 9E991 BOEING PROPRIETARY - See title page for details.



3 33215174 SHT 6 REV 000

LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 6)

33-21-51-74



3 33215174 SHT 7 REV 022

LIGHT INSTL-LED SIDEWALL MID
FIGURE 74 (SHEET 7)

33-21-51-74

RJR
JUL 15/18

33-21-51-74
PAGE 0F

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
74			LIGHT INSTL-LED SIDEWALL MID		
- 1	MODREF702616		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5505-48001 REV A POSITION DATA: MID	001037	RF
- 1	MODREF828154		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5505-48001 REV B POSITION DATA: MID	038999	RF
5	BAC29PPS0347		.DECAL- PLACARD CONTENT: L751 OVERHATCH EXIT SIGN		4
13	BACS12ER3K10		.SCREW		40
14	BACS12ER3K12		.SCREW		4
16	BACS12GU3K7		.SCREW		4
18	BACS12FA3K5		.SCREW		102
19	BACS12FA3K6		.SCREW		2
20	NAS1149D0316J		.WASHER		4
23	69-66047-1		.WASHER-RTNR		72
24	BACC15BFA		.CRADLE- POSITION DATA: RH SIDE		1
25	71320-02		.RETAINER-LENS SUPPLIER CODE: V59579		4
30	71320-03		.RETAINER-LENS SUPPLIER CODE: V59579		4
35	71320-08		.RETAINER-LENS SUPPLIER CODE: V59579		32
40	6047-001		.LENS- SUPPLIER CODE: V59579		2
45	6047-006		.LENS- SUPPLIER CODE: V59579		2
50	6047-010		.LENS- SUPPLIER CODE: V59579		2
55	6047-024		.LENS- SUPPLIER CODE: V59579		2
60	6047-027		.LENS- SUPPLIER CODE: V59579		8
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-51-74

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
FIG. 74
PAGE 1
MAR 15/20

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
74					
65	6047-032	. LENS-			4
		SUPPLIER CODE:			
		V59579			
70	6047-036	. LENS-			10
		SUPPLIER CODE:			
		V59579			
75	6047-038	. LENS-			2
		SUPPLIER CODE:			
		V59579			
80	6047-055	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		LH SIDE			
85	6047-056	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		RH SIDE			
90	6047-057	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		RH SIDE			
95	6047-058	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		LH SIDE			
100	6047-065	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		LH SIDE			
105	6047-067	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		RH SIDE			
110	6047-068	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		RH SIDE			
115	6047-069	. LENS-			1
		SUPPLIER CODE:			
		V59579			
		POSITION DATA:			
		LH SIDE			
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

RYR

33-21-51-74

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51
FIG. 74
PAGE 2
MAR 15/20

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
74					
117	417A5464-49		.SHIELD		44
120	PLT1-5IM		.STRAP		AR
			SUPPLIER CODE: V06383		
			SPECIFICATION NUMBER: BACS38K5		
			OPTIONAL PART: T03R0		
			V53421		
125	417N5107-2		.GROMMET		2
130	71289-00		.BRACKET ASSY-		32
			SUPPLIER CODE: V59579		
			MISCELLANEOUS DATA: Q659A4791-3 IS BOEING PREFERRED SPARE PART.		
130	71289LS01-00		.BRACKET ASSY-		32
			SUPPLIER CODE: V59579		
130	Q659A4791-3		.BRACKET ASSY-		32
135	65C33259-157		.BRACKET ASSY-LENS SPRT		1
			POSITION DATA: LH SIDE		
140	65C33259-158		.BRACKET ASSY-LENS SPRT		1
			POSITION DATA: RH SIDE		
145	130069		..NUT		1
			SUPPLIER CODE: V60119		
			SPECIFICATION NUMBER: BACN10FX16		
			OPTIONAL PART: A11330-6-3		
			V72962		
			A4972-6-02		
			V72962		
150	65C33259-155		..BRACKET-		1
			POSITION DATA: LH SIDE		
- 152	65C33259-156		..BRACKET-		1
			POSITION DATA: RH SIDE		
155	65C33259-161		.BRACKET ASSY-LT SPRT		1
			POSITION DATA: LH SIDE		
160	65C33259-162		.BRACKET ASSY-LT SPRT		1
			POSITION DATA: RH SIDE		
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

R Y R

33-21-51-74

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
FIG. 74
PAGE 3
NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
74 165	130069	..	NUT SUPPLIER CODE: V60119 SPECIFICATION NUMBER: BACN10FX16 OPTIONAL PART: A11330-6-3 V72962 A4972-6-02 V72962		1
170	65C33259-159	..	BRACKET- POSITION DATA: LH SIDE		1
- 172	65C33259-160	..	BRACKET- POSITION DATA: RH SIDE		1
175	BACS12ER06K8WT	.	SCREW		8
180	BACS12FA3K8WH	.	SCREW		16
187	BRC600-8-3	.	NUT SUPPLIER CODE: V52828 SPECIFICATION NUMBER: BACN10YD1 OPTIONAL PART: 130120 V60119		16
190	5862-00	.	LENS ASSY-OVER WING EXIT SUPPLIER CODE: V59579		4
205	9651-14-0005	.	LIGHT ASSY-14 IN. TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 14" ELECTRICAL EQUIP NUMBER: M02832 COMPONENT MAINT MANUAL REF: 33-20-43 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-02		4
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

R Y R

33-21-51-74

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
FIG. 74
PAGE 4
JUL 15/18

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7 NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
74 210	9651-35-0002	.LIGHT ASSY-35 IN. TYPE C CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE C CONN 35" ELECTRICAL EQUIP NUMBER: M02819 COMPONENT MAINT MANUAL REF: 33-20-43 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-05		14
215	9651-35-0003	.LIGHT ASSY-35 IN. TYPE D CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE D CONN 35" ELECTRICAL EQUIP NUMBER: M02820 COMPONENT MAINT MANUAL REF: 33-20-43 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-05		4
220	9651-35-0004	.LIGHT ASSY-35 IN. TYPE E CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE E CONN 35" ELECTRICAL EQUIP NUMBER: M02817 COMPONENT MAINT MANUAL REF: 33-20-43 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-06		4
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE				

— ITEM NOT ILLUSTRATED

R Y R

33-21-51-74

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51
FIG. 74
PAGE 5
JAN 15/21

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
74 225	9651-35-0005		.LIGHT ASSY-35 IN. TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 35" ELECTRICAL EQUIP NUMBER: M02799 COMPONENT MAINT MANUAL REF: 33-20-43 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-06		10
380	9701-14-0000		.LIGHT ASSY-OVER WING EXIT TYPE B CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 OVER WING EXIT LIGHT TYPE B CONN ELECTRICAL EQUIP NUMBER: M02838 COMPONENT MAINT MANUAL REF: 33-20-44 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-10		2
385	9701-14-0001		.LIGHT ASSY-OVER WING EXIT TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 OVER WING EXIT LIGHT TYPE F CONN ELECTRICAL EQUIP NUMBER: M02837 COMPONENT MAINT MANUAL REF: 33-20-44 MAINTENANCE MANUAL REF: 33-21-00 FOR DETAILS SEE: 33-21-52-11		2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					


— ITEM NOT ILLUSTRATED

R Y R

33-21-51-74

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51
FIG. 74
PAGE 6
JAN 15/21




3 33215175A SHT 1 REV 038

LIGHT INSTL-LED SIDEWALL AFT LH
FIGURE 75A (SHEET 1)

33-21-51-75A

R/YR
MAR 15/19

33-21-51-75A
PAGE 0




3 33215175A SHT 2 REV 038

LIGHT INSTL-LED SIDEWALL AFT LH
FIGURE 75A (SHEET 2)

33-21-51-75A

R/YR
MAR 15/19

33-21-51-75A
PAGE 0A



3 33215175A SHT 3 REV 038

LIGHT INSTL-LED SIDEWALL AFT LH
FIGURE 75A (SHEET 3)

33-21-51-75A

R/YR
MAR 15/19

33-21-51-75A
PAGE 0B

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
75A			LIGHT INSTL-LED SIDEWALL AFT LH		
- 1	MODREF776057		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5506-43010 REV A POSITION DATA: AFT LH	001037	RF
- 1	MODREF827624		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5506-43010 REV B POSITION DATA: AFT LH	038999	RF
5	BACC63EJ01A		.PLUG		1
15	BACS12ER3K10		.SCREW		4
20	BACS12FA3K5		.SCREW		8
25	69-66047-1		.WASHER-RTNR		6
30	71320-08		.RETAINER-LENS SUPPLIER CODE: V59579		3
35	71320-05		.RETAINER-LENS SUPPLIER CODE: V59579		1
40	6047-062		.LENS- SUPPLIER CODE: V59579		1
45	6047-027		.LENS- SUPPLIER CODE: V59579		1
50	6047-031		.LENS- SUPPLIER CODE: V59579		1
55	6047-076		.LENS- SUPPLIER CODE: V59579		1
60	417A5464-49		.SHIELD		4
65	PLT1-5IM		.STRAP SUPPLIER CODE: V06383 SPECIFICATION NUMBER: BACS38K5 OPTIONAL PART: T03R0 V53421		AR
70	417N5107-2		.GROMMET		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-51-75A

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
FIG. 75A
PAGE 1
NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7 NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
75A 75	71289-00	.BRACKET ASSY- SUPPLIER CODE: V59579 MISCELLANEOUS DATA: Q659A4791-3 IS BOEING PREFERRED SPARE PART.		2
75	71289LS01-00	.BRACKET ASSY- SUPPLIER CODE: V59579		2
75 80	Q659A4791-3 9651-35-0005	.BRACKET ASSY- .LIGHT ASSY-35 IN. TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 35" ELECTRICAL EQUIP NUMBER: M02799 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-06		2 1
85	9651-35-0001	.LIGHT ASSY-35 IN. TYPE B CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE B CONN 35" ELECTRICAL EQUIP NUMBER: M02818 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-05		1
90	9651-14-0003	.LIGHT ASSY-14 IN. TYPE D CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE D CONN 14" ELECTRICAL EQUIP NUMBER: M02831 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-01		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE				


— ITEM NOT ILLUSTRATED

R Y R

33-21-51-75A

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51
 FIG. 75A
 PAGE 2
 NOV 15/20



3 33215177A SHT 1 REV 046


LIGHT INSTL-LED SIDEWALL AFT RH
FIGURE 77A (SHEET 1)

R Y R
NOV 15/19

33-21-51-77A


ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51-77A
PAGE 0




33-21-51-77A

ECCN 9E991 BOEING PROPRIETARY – See title page for details.



FWD

(B)



FWD

(C)

3 33215177A SHT 3 REV 038

LIGHT INSTL-LED SIDEWALL AFT RH
FIGURE 77A (SHEET 3)

33-21-51-77A

R/YR
MAR 15/19

33-21-51-77A
PAGE 0B

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
77A					
- 1	MODREF776058		LIGHT INSTL-LED SIDEWALL AFT RH	001037	RF
- 1	MODREF827623		LIGHT INSTL-LED SIDEWALL MODULE NUMBER: 417A5506-44009 REV A POSITION DATA: STA 821.38 TO 927.67, AFT RH	038999	RF
10	BACS12ER3K10		.SCREW		4
15	BACS12FA3K5		.SCREW		8
20	69-66047-1		.WASHER-RTNR		6
25	71320-08		.RETAINER-LENS SUPPLIER CODE: V59579		3
30	71320-04		.RETAINER-LENS SUPPLIER CODE: V59579		1
35	6047-059		.LENS- SUPPLIER CODE: V59579		1
40	6047-027		.LENS- SUPPLIER CODE: V59579		1
45	6047-031		.LENS- SUPPLIER CODE: V59579		1
50	6047-076		.LENS- SUPPLIER CODE: V59579		1
55	417A5464-49		.SHIELD		4
60	PLT1-5IM		.STRAP SUPPLIER CODE: V06383 SPECIFICATION NUMBER: BACS38K5 OPTIONAL PART: T03R0 V53421		AR
65	417N5107-2		.GROMMET		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-51-77A

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-51
 FIG. 77A
 PAGE 1
 NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
77A					
70	71289-00		.BRACKET ASSY- SUPPLIER CODE: V59579 MISCELLANEOUS DATA: Q659A4791-3 IS BOEING PREFERRED SPARE PART.		2
70	71289LS01-00		.BRACKET ASSY- SUPPLIER CODE: V59579		2
70	Q659A4791-3		.BRACKET ASSY-		2
75	417A5464-31		.HOOK-WIRE SPRT		6
80	9651-35-0005		.LIGHT ASSY-35 IN. TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 35" ELECTRICAL EQUIP NUMBER: M02799 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-06		1
85	9651-35-0001		.LIGHT ASSY-35 IN. TYPE B CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE B CONN 35" ELECTRICAL EQUIP NUMBER: M02818 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-05		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

R Y R

33-21-51-77A

ECCN 9E991 BOEING PROPRIETARY — See title page for details.

33-21-51
 FIG. 77A
 PAGE 2
 NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
77A 90	9651-14-0003		.LIGHT ASSY-14 IN. TYPE D CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE D CONN 14" ELECTRICAL EQUIP NUMBER: M02831 COMPONENT MAINT MANUAL REF: 33-20-43 FOR DETAILS SEE: 33-21-52-01		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED


R Y R

33-21-51-77A

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-51
 FIG. 77A
 PAGE 3
 NOV 15/20

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG



3 33215201 SHT 1 REV 024


LIGHT ASSY-14 IN. SIDEWALL
FIGURE 1 (SHEET 1)

33-21-52-01

R/YR
MAR 15/19

33-21-52-01
PAGE 0

ECCN 9E991 BOEING PROPRIETARY - See title page for details.



(B)

3 33215201 SHT 2 REV 024

LIGHT ASSY-14 IN. SIDEWALL
FIGURE 1 (SHEET 2)

33-21-52-01

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

RJR
MAR 15/19

33-21-52-01
PAGE 0A

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1					
- 5	9651-14-0003		LIGHT ASSY-14 IN. SIDEWALL LIGHT ASSY-14 IN. TYPE D CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE D CONN 14" ELECTRICAL EQUIP NUMBER: M02831 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-75A 33-21-51-77A		RF
50	61728-15		. LABEL-TYPE D SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-65 USED ON: 9651-14-0003		1
50	61728-65		. LABEL-TYPE D SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-15 USED ON: 9651-14-0003		1
55	61813-03		. LABEL-SIDEWALL, TYPE D SUPPLIER CODE: V59579 USED ON: 9651-14-0003		1
60	71290-00		. BRACKET ASSY-END MTG SUPPLIER CODE: V59579		2
65	MS20426AD3-3		.. RIVET- STANDARD SUBSTITUTION: BACR15BA3AD3C CONFIG CHG DATA FROM A CMM: SUPSD BY AN426AD3-3DW		2
65	AN426AD3-3DW		.. RIVET- CONFIG CHG DATA FROM A CMM: SUPERSEDES MS20426AD3-3		2
70	5352-00		.. CLIP-SPR SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-52-01

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-52
FIG. 01
PAGE 1
MAY 15/23

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
1					
75	71288-00		..BRACKET- SUPPLIER CODE: V59579		1
100	9201-13-0003		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-14-0003		1
105	5317-02		..CAP-END SUPPLIER CODE: V59579		2
105	5318-00		..CAP-END SUPPLIER CODE: V59579		2
110	6045-13		..LENS-13 IN. SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED



R Y R

33-21-52-01

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
 FIG. 01
 PAGE 2
 MAY 15/23

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG



3 33215202 SHT 1 REV 022


LIGHT ASSY-14 IN. SIDEWALL
FIGURE 2 (SHEET 1)

33-21-52-02

RJR
JUL 15/18

33-21-52-02
PAGE 0

ECCN 9E991 BOEING PROPRIETARY – See title page for details.



(B)

3 33215202 SHT 2 REV 022

LIGHT ASSY-14 IN. SIDEWALL
FIGURE 2 (SHEET 2)

33-21-52-02

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

RJR
JUL 15/18

33-21-52-02
PAGE 0A

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
- 1	9651-14-0004		LIGHT ASSY-14 IN. SIDEWALL LIGHT ASSY-14 IN. TYPE E CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE E CONN 14" ELECTRICAL EQUIP NUMBER: M02800 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-71 33-21-51-71A		RF
- 5	9651-14-0005		LIGHT ASSY-14 IN. TYPE F CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 14" ELECTRICAL EQUIP NUMBER: M02832 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-74		RF
50	61728-16		. LABEL-TYPE E SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-66 USED ON: 9651-14-0004		1
50	61728-66		. LABEL-TYPE E SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-16 USED ON: 9651-14-0004		1
50	61728-17		. LABEL-TYPE F SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-67 USED ON: 9651-14-0005		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

R Y R

33-21-52-02

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-52
FIG. 02
PAGE 1
JUL 15/18

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
50	61728-67		.LABEL-TYPE F SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-17 USED ON: 9651-14-0005		1
55	61813-04		.LABEL-SIDEWALL, TYPE E SUPPLIER CODE: V59579 USED ON: 9651-14-0004		1
55	61813-05		.LABEL-SIDEWALL, TYPE F SUPPLIER CODE: V59579 USED ON: 9651-14-0005		1
60	71290-00		.BRACKET ASSY-END MTG SUPPLIER CODE: V59579		2
65	MS20426AD3-3		..RIVET- STANDARD SUBSTITUTION: BACR15BA3AD3C CONFIG CHG DATA FROM A CMM: SUPSD BY AN426AD3-3DW		2
65	AN426AD3-3DW		..RIVET- CONFIG CHG DATA FROM A CMM: SUPERSEDES MS20426AD3-3		2
70	5352-00		..CLIP-SPR SUPPLIER CODE: V59579		1
75	71288-00		..BRACKET- SUPPLIER CODE: V59579		1
100	9201-13-0004		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-14-0004		1
100	9201-13-0005		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-14-0005		1
105	5317-02		..CAP-END SUPPLIER CODE: V59579		2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

R Y R

33-21-52-02

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
FIG. 02
PAGE 2
MAR 15/23

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
105	5318-00		..CAP-END SUPPLIER CODE: V59579		2
110	6045-13		..LENS-13 IN. SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED


R Y R

33-21-52-02

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
 FIG. 02
 PAGE 3
 JUL 15/18

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG



3 33215205 SHT 1 REV 022


LIGHT ASSY-35 IN. SIDEWALL
FIGURE 5 (SHEET 1)

33-21-52-05

R Y R
M A Y 15 / 18

33-21-52-05
P A G E 0

ECCN 9E991 BOEING PROPRIETARY - See title page for details.



3 33215205 SHT 2 REV 022

LIGHT ASSY-35 IN. SIDEWALL
FIGURE 5 (SHEET 2)

RJR
MAY 15/18

33-21-52-05

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52-05
PAGE 0A

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
5					
- 5	9651-35-0001		LIGHT ASSY-35 IN. SIDEWALL LIGHT ASSY-35 IN. TYPE B CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE B CONN 35" ELECTRICAL EQUIP NUMBER: M02818 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-71 33-21-51-71A 33-21-51-75A 33-21-51-77A		RF
- 10	9651-35-0002		LIGHT ASSY-35 IN. TYPE C CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE C CONN 35" ELECTRICAL EQUIP NUMBER: M02819 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-74		RF
- 15	9651-35-0003		LIGHT ASSY-35 IN. TYPE D CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE D CONN 35" ELECTRICAL EQUIP NUMBER: M02820 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-74		RF
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

RYR

33-21-52-05

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
FIG. 05
PAGE 1
MAR 15/19

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
5					
50	61728-23		.LABEL-TYPE B SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-73 USED ON: 9651-35-0001		1
50	61728-73		.LABEL-TYPE B SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-23 USED ON: 9651-35-0001		1
50	61728-24		.LABEL-TYPE C SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-74 USED ON: 9651-35-0002		1
50	61728-74		.LABEL-TYPE C SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-24 USED ON: 9651-35-0002		1
50	61728-25		.LABEL-TYPE D SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-75 USED ON: 9651-35-0003		1
50	61728-75		.LABEL-TYPE D SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-25 USED ON: 9651-35-0003		1
55	61813-11		.LABEL-SIDEWALL, TYPE B SUPPLIER CODE: V59579 USED ON: 9651-35-0001		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

RYR

33-21-52-05

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
FIG. 05
PAGE 2
MAR 15/19

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
5					
55	61813-12		.LABEL-SIDEWALL, TYPE C SUPPLIER CODE: V59579 USED ON: 9651-35-0002		1
55	61813-13		.LABEL-SIDEWALL, TYPE D SUPPLIER CODE: V59579 USED ON: 9651-35-0003		1
60	71290-00		.BRACKET ASSY-END MTG SUPPLIER CODE: V59579		2
65	MS20426AD3-3		..RIVET- STANDARD SUBSTITUTION: BACR15BA3AD3C CONFIG CHG DATA FROM A CMM: SUPSD BY AN426AD3-3DW		2
65	AN426AD3-3DW		..RIVET- CONFIG CHG DATA FROM A CMM: SUPERSEDES MS20426AD3-3		2
70	5352-00		..CLIP-SPR SUPPLIER CODE: V59579		1
75	71288-00		..BRACKET- SUPPLIER CODE: V59579		1
100	9201-34-0001		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-35-0001		1
100	9201-34-0002		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-35-0002		1
100	9201-34-0003		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-35-0003		1
105	5317-02		..CAP-END SUPPLIER CODE: V59579		2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

RYR

33-21-52-05

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
FIG. 05
PAGE 3
MAR 15/23

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
5					
105	5318-00		..CAP-END SUPPLIER CODE: V59579		2
110	6045-34		..LENS-34 IN. FLAT SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					


— ITEM NOT ILLUSTRATED

RYR

33-21-52-05

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
 FIG. 05
 PAGE 4
 MAR 15/19




3 33215206 SHT 1 REV 022

LIGHT ASSY-35 IN. SIDEWALL
FIGURE 6 (SHEET 1)

33-21-52-06

RJR
MAY 15/18

33-21-52-06
PAGE 0



(B)

3 33215206 SHT 2 REV 022

LIGHT ASSY-35 IN. SIDEWALL
FIGURE 6 (SHEET 2)

33-21-52-06

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

R Y R
M A Y 15 / 18

33-21-52-06
P A G E 0 A

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
6					
- 1	9651-35-0004		LIGHT ASSY-35 IN. SIDEWALL LIGHT ASSY-35 IN. TYPE E CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE E CONN 35" ELECTRICAL EQUIP NUMBER: M02817 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-74		RF
- 5	9651-35-0005		LIGHT ASSY-35 IN. TYPE F CONN. SIDEWALL SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 SIDEWALL LIGHT TYPE F CONN 35" ELECTRICAL EQUIP NUMBER: M02799 COMPONENT MAINT MANUAL REF: 33-20-43 FOR NHA SEE: 33-21-51-71 33-21-51-71A 33-21-51-74 33-21-51-75A 33-21-51-77A		RF
50	61728-26		. LABEL-TYPE E SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-76 USED ON: 9651-35-0004		1
50	61728-76		. LABEL-TYPE E SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-26 USED ON: 9651-35-0004		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-52-06

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-52
FIG. 06
PAGE 1
MAR 15/19

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
6					
50	61728-27		. LABEL-TYPE F SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPSD BY 61728-77 USED ON: 9651-35-0005		1
50	61728-77		. LABEL-TYPE F SUPPLIER CODE: V59579 CONFIG CHG DATA FROM A CMM: SUPERSEDES 61728-27 USED ON: 9651-35-0005		1
55	61813-14		. LABEL-SIDEWALL, TYPE E SUPPLIER CODE: V59579 USED ON: 9651-35-0004		1
55	61813-15		. LABEL-SIDEWALL, TYPE F SUPPLIER CODE: V59579 USED ON: 9651-35-0005		1
60	71290-00		. BRACKET ASSY-END MTG SUPPLIER CODE: V59579		2
65	MS20426AD3-3		.. RIVET- STANDARD SUBSTITUTION: BACR15BA3AD3C CONFIG CHG DATA FROM A CMM: SUPSD BY AN426AD3-3DW		2
65	AN426AD3-3DW		.. RIVET- CONFIG CHG DATA FROM A CMM: SUPERSEDES MS20426AD3-3		2
70	5352-00		.. CLIP-SPR SUPPLIER CODE: V59579		1
75	71288-00		.. BRACKET- SUPPLIER CODE: V59579		1
100	9201-34-0004		. ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-35-0004		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

RYR

33-21-52-06

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
 FIG. 06
 PAGE 2
 MAR 15/23

BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
6					
100	9201-34-0005		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579 USED ON: 9651-35-0005		1
105	5317-02		..CAP-END SUPPLIER CODE: V59579		2
105	5318-00		..CAP-END SUPPLIER CODE: V59579		2
110	6045-34		..LENS-34 IN. FLAT SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					


— ITEM NOT ILLUSTRATED

R Y R

33-21-52-06

ECCN 9E991 BOEING PROPRIETARY – See title page for details.

33-21-52
 FIG. 06
 PAGE 3
 JUL 15/18




3 33215210 SHT 1 REV 022

LIGHT ASSY-OVER WING EXIT TYPE B CONN.
FIGURE 10 (SHEET 1)


33-21-52-10

RJR
JUL 15/18

33-21-52-10
PAGE 0



(A)



(B)

3 33215210 SHT 2 REV 022

LIGHT ASSY-OVER WING EXIT TYPE B CONN.
FIGURE 10 (SHEET 2)

33-21-52-10

RJR
JUL 15/18

33-21-52-10
PAGE 0A

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
10			LIGHT ASSY-OVER WING EXIT TYPE B CONN.		
- 1	9701-14-0000		LIGHT ASSY-OVER WING EXIT TYPE B CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 OVER WING EXIT LIGHT TYPE B CONN ELECTRICAL EQUIP NUMBER: M02838 COMPONENT MAINT MANUAL REF: 33-20-44 FOR NHA SEE: 33-21-51-74		RF
50	61728-78		.LABEL- SUPPLIER CODE: V59579		1
55	5352-00		.CLIP-SPR SUPPLIER CODE: V59579		2
60	MS16535-77		ATTACHING PARTS .RIVET -----*-----		4
65	5863-00		.HOUSING- SUPPLIER CODE: V59579		1
70	8860		.CLIP-CABLE TIE ROUTING SUPPLIER CODE: V91833 OPTIONAL SUPPLIER CODE: 59579		3
75	0652W6		.GROMMET- SUPPLIER CODE: V59579		2
100	9251-13-0000		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579		1
105	5317-02		..CAP- SUPPLIER CODE: V59579		2
105	5318-00		..CAP- SUPPLIER CODE: V59579		2
110	6045-13		..LENS-13 IN. FLAT SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					


- ITEM NOT ILLUSTRATED

RYR

33-21-52-10

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-52
FIG. 10
PAGE 1
JUL 15/18




3 33215211 SHT 1 REV 022

LIGHT ASSY-OVER WING EXIT TYPE F CONN.
FIGURE 11 (SHEET 1)


33-21-52-11

RJR
JUL 15/18

33-21-52-11
PAGE 0



(A)



(B)

3 33215211 SHT 2 REV 022

LIGHT ASSY-OVER WING EXIT TYPE F CONN.
FIGURE 11 (SHEET 2)

33-21-52-11

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

 BOEING
737-7/8/8200/9/10
ILLUSTRATED PARTS CATALOG

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
11			LIGHT ASSY-OVER WING EXIT TYPE F CONN.		
- 1	9701-14-0001		LIGHT ASSY-OVER WING EXIT TYPE F CONN. SUPPLIER CODE: V59579 FUNCTIONAL DESCRIPTION: BSI GEN2 OVER WING EXIT LIGHT TYPE F CONN ELECTRICAL EQUIP NUMBER: M02837 COMPONENT MAINT MANUAL REF: 33-20-44 FOR NHA SEE: 33-21-51-74		RF
50	61728-79		.LABEL- SUPPLIER CODE: V59579		1
55	5352-00		.CLIP-SPR SUPPLIER CODE: V59579		2
60	MS16535-77		ATTACHING PARTS .RIVET -----*-----		4
65	5863-00		.HOUSING- SUPPLIER CODE: V59579		1
70	8860		.CLIP-CABLE TIE ROUTING SUPPLIER CODE: V91833 OPTIONAL SUPPLIER CODE: 59579		3
75	0652W6		.GROMMET- SUPPLIER CODE: V59579		2
100	9251-13-0001		.ELEMENT ASSY-RGB+W LIGHTING SUPPLIER CODE: V59579		1
105	5317-02		..CAP- SUPPLIER CODE: V59579		2
105	5318-00		..CAP- SUPPLIER CODE: V59579		2
110	6045-13		..LENS-13 IN. FLAT SUPPLIER CODE: V59579		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

RYR

33-21-52-11

ECCN 9E991 BOEING PROPRIETARY - See title page for details.

33-21-52
FIG. 11
PAGE 1
NOV 15/21