

CATERPILLAR 304 CR SERVICE MANUAL (EXCERPT)

Code No. SEBU8407-05 / Issued 2023-05 / Caterpillar Inc. (excerpt for training)

SEAT BELT INSPECTION

Inspect the seat belt and the attaching hardware before each shift. Replace the seat belt within three years of the date on the belt tag, regardless of appearance.

The tag is attached to the belt webbing near the buckle and shows the month and year of manufacture.

TRACK ADJUSTMENT

Measure the track sag at the midpoint between the carrier roller and the idler. The specified sag is 10 to 15 mm. Adjust with grease through the track adjuster fitting.