
Find a kitchen

Q search

3 kitchen(s) found




Kochschule Meier & Huber

150 Devices

Kontakt immer mit Herrn Meier

last used 2015-02-03




Restaurant Grosser Adler

5 Devices

Eigenen Stromverteiler mitnehmen.

last used 2015-01-12




Gourmet-Tempel Oberberg

15 Devices

Parkplatz hinter dem Haus

last used 2015-06-30



Testlabor Amriswil (3B)

2 Devices

Nur temporär zum Testen.

last used 2015-02-03



Create a new kitchen

Name

Baumwald Genusswelten


Description


Grosse Installation auf Showfloor. Wurde von Martin Muster installiert.

+

Tap this rectangle to add an image of the kitchen.

Create >





← Kitchen Overview



MIA Induction

FLX_123

0


FLX_1345

C Class Induction REX

FLX_12323

ET Series Thermostate


FLX_12fd3



← Device Status



Show Usage Statistics
Show Error History
Change Settings



← Change Settings



Setting 1	
195 °C	
	_
Setting 2	
489 W	
	_
Setting 3	
466 V	
	_
Setting 4	
23 A	
	_
Setting 5	
Some sample Text	
	_
Setting 6	
2.3	
	_
Setting 7	
95 °C	
	_

Usage statistics



Uptime

100 % Power On Time 2d 12:03:15

53 %

Working Time

1d 10:32:07

Heatsink temperature

80 % 10:03:15

< 60 °C

60 - 69 °C

10 % 1d 10:32:07

7 % 70 - 79 °C 2d 10:03:15

3 % > 80 - C 1d 10:32:07

Glass temperature

80 % 10:03:15

< 60 °C

60 - 69 °C

10 % 1d 10:32:07

← Error History



E03 Device temperature above 80 °C 2d 12:03:15

E01 No pan detected 2d 11:03:15

E06 Maximum usage time expired 2d 11:02:15

E11 Communication malfunction 2d 10:03:15

E13 Temperature measurment failure 2d 09:03:15

E03 Environment temperature above 80 °C 2d 09:00:45

E01 No pan detected

E19 Coil power connection malfunction 2d 12:03:15

E18 Please contact the manufacturer 2d 12:03:15

E15 Coil zone interference 2d 12:03:15