

# Overheating Troubleshooting Guide

Use this guide when telemetry indicates a motor stator or bearing temperature exceeds normal operating thresholds (typically > 85°C).

## Common Causes and Actions

| Root Cause                | Diagnostic Evidence                                               | Recommended Action                                                     |
|---------------------------|-------------------------------------------------------------------|------------------------------------------------------------------------|
| Mechanical Overload       | High current (Amps) correlating with high temperature.            | Reduce load. Check driven equipment for mechanical binding.            |
| Blocked Ventilation       | Normal current, but high stator temperature.                      | Clean motor cooling fins. Verify cooling fan integrity.                |
| Bearing Impending Failure | Localized heat at bearing housing; high high-frequency vibration. | Execute Bearing Inspection SOP. Schedule downtime for replacement.     |
| Voltage Imbalance         | Unequal phase currents; rapid heating.                            | Check power supply. Verify phase voltages are within 1% of each other. |

