

ISO 10816 Vibration Severity Chart

Standard thresholds for rigid-mounted industrial electric motors (15kW - 300kW).

Vibration Velocity (RMS mm/s)	Machine Condition	Required Action
0.0 - 1.8	Zone A: Excellent	None. Machine is healthy.
1.8 - 4.5	Zone B: Acceptable	Standard monitoring. Safe for continuous operation.
4.5 - 7.1	Zone C: Restricted	Elevated risk. Plan remedial action during next maintenance window.
> 7.1	Zone D: Damage Risk	Immediate shutdown recommended. High risk of bearing or structural failure.

